






### General information

Make	PEUGEOT
Model	BOXER HDI 350 LX XLWB C/C
Colour	White
Year of manufacture	2006
Gearbox	5 speed MANUAL

# Engine & fuel consumption

Max. torque	9999 Nm at 9.999 rpm
Engine capacity	2.800 cc
Cylinders	4
Fuel type	Diesel







Internet history	
Entry 1	
Date	2021-02-03
Pictures	1
Listing price	View report



source: autoonline.co.uk



## MOT history

MOT expiry date	2025-01-13
MOT pass rate	71 %
MOT passed	17
Failed MOT tests	7
Total advice items	17
Total items failed	15

MOT #24	2023-12-18 11:39
MOT test number	254340001878
Result	✓ Passed
Next expiry date	2025-01-13

MOT #23		2022-12-15 09:54
MOT test i	number	686018310137
Result		✓ Passed
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		.1.14 (a) (ii))
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))	

MOT #22	2022-12-15 09:54	
MOT test number	690507646717	
Result	× Failed	
<b>Pass with rectification</b> longer prevents the ingress	Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no of dirt (6.1.7 (g) (ii))	
Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice Offside Front Service brake binding but not excessively (1.2.1 (f))		
Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Pass with rectification	Offside Headlamp aim too low (4.1.2 (a))	





MOT #21		2022-01-14 10:14
MOT test	number	189418735116
Result		✓ Passed
Advice	Offside Power steering pipe/hose slightly corroded from pump to rack (2.1.5 (g) (i)	)
Advice	Nearside Inner Power steering ram components slightly misaligned (2.1.5 (e) (i))	
Advice	Nearside Front Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Offside Inner Power steering ram has slight seepage from a joint (2.1.5 (a))	

МОТ #20	2021-02-15 11:25
MOT test number	201966024611
Result	✓ Passed
<b>Advice</b> Nearside Front Integral body structure is corroded but structural rigidity is not significantly reduced lower leg/inner wheel arch corroded within 30 cm of front sub-frame mounting point (6.1.1 (c) (i))	

MOT #19	2020-02-14 11:03
MOT test number	642607468443
Result	✓ Passed
MOT #18	2019-03-25 10:17
MOT test number	538353103568
Result	✓ Passed
MOT #17	2018-03-15 13:29
MOT test number	331083814490
Result	✓ Passed
Advice Exhaust rubber mounts perishing	





MOT #16		2018-03-15 13:29
MOT test number		241847132596
Result		🗙 Failed
Pass with rectification	Offside Rear Stop lamp not working (1.2.1b)	
Advice Exhaust rubber	mounts perishing	
MOT #15		2017-04-07 16:27
MOT test number		870301107670
Result		✓ Passed
MOT #14		2016-11-22 15:25
MOT test number		955459898592
Result		✓ Passed
MOT #13		2016-11-21 12:20
MOT test number		241048069862
Result		🗙 Failed
Fail Front Exhaust has a	a major leak of exhaust gases (7.1.2)	

MOT #12	2015-11-24 09:45
MOT test number	269344725769
Result	✓ Passed
MOT #11	2014-11-26 09:55
MOT test number	306520834308
Result	✓ Passed

2013-12-10 10:04
969334043342
✓ Passed





MOT #9		2013-05-10 09:00
MOT test number		915590733143
Result		✓ Passed
МОТ #8		2013-05-10 09:00
MOT test number		255700533149
Result		🗙 Failed
Pass with rectification	Nearside Rear Direction indicator not working (1.4.A.2c)	
Pass with rectification	Exhaust system not adequately supported (7.1.1)	
Pass with rectification	Offside Rear Rear position lamp(s) not working (1.1.A.3b)	

MOT #7	2012-05-03 17:58
MOT test number	655084222141
Result	× Failed
Pass with rectification	Centre Exhaust system not adequately supported (7.1.1)
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

МОТ #6	2012-05-03 17:58
MOT test number	345034322181
Result	✓ Passed





MOT #5		2011-08-16 12:05
MOT test number		897408821203
Result		🗙 Failed
Pass with rectification	Nearside Headlamp aim too low (1.8)	
<b>Notice</b> All tyres perished	b	
Pass with rectification	Horn not working (1.6.2a)	
Pass with rectification	Offside Headlamp aim too low (1.8)	

МОТ #4	2011-08-16 12:05
MOT test number	188408621240
Result	✓ Passed
Notice All tyres perished	

MOT #3	2010-09-15 17:03
MOT test number	322758250411
Result	✓ Passed

MOT #2	2009-07-16 15:04
MOT test number	454327699122
Result	✓ Passed
<b>Notice</b> Exhaust mounts deteriorated and just supporting exhaust	

MOT #1	2009-07-16 15:04
MOT test number	151637599196
Result	× Failed
Notice Exhaust mounts	deteriorated and just supporting exhaust
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓ Taxed Tax due: 1 April 2025	<b>MOT</b> <b>Expires:</b> 13 January 2025
Tax status	Valid until 1 April
Days left	337
MOT expiry date	13 January 2025
Full MOT history	See MOT history





### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	4. DEM PE
Туре	
Damage 2	Annet
Date	No. Contraction of the second
Category	AMP
Туре	

#### Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





## Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	
**********	
*******	
******	
**********	
*******	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-05-30
Last registration	2023-12-18
Complete history	See info



Registration #1	2006-05-30	8 mi
Registration #2	2009-07-16	5.518 mi
Registration #3	2010-09-15	5.748 mi
Registration #4	2011-08-16	6.767 mi
Registration #5	2012-05-03	8.021 mi
Registration #6	2013-05-10	9.608 mi
Registration #7	2013-12-10	12.078 mi
Registration #8	2014-11-26	16.138 mi
Registration #9	2015-11-24	19.988 mi
Registration #10	2016-11-21	23.376 mi
Registration #11	2016-11-22	23.376 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.777 esi
Registration #19		11.777 mi
Registration #20		11.777 est
Registration #21		11.777 mi
Registration #22		11.777 est





## Car features

50225	Air conditioning
50295	
50482	
60501	
0566	
60567	
0569	

Dimensions & weight	
Width	2024 mm
Max. allowed weight	3500 kg
Additional information	
Number of seats	2
Number of axles	2
Engine number	22204115185