





report date: 2022-08-09

## General information

Make	MASERATI
Model	COUPE V8 SPYDER
Colour	Yellow
Year of manufacture	2004
Top speed	174 mph
0 - 60 mph	4.9 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	385 BHP
Max. torque	450 Nm at 4.500 rpm
Engine capacity	4.244 cc
Cylinders	8
Fuel type	Petrol
Consumption city	10.0 mpg
Consumption extra urban	21.7 mpg
Consumption combined	15.2 mpg
CO2 emission	430 g/km
CO2 label	М



CarCheck.co.uk page 1/14



report date: 2022-08-09

## Internet history

## Entry 1

Date 2022-05-17

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/14



report date: 2022-08-09

**MOT** history

MOT expiry date	2024-06-14
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	29
Total items failed	9

MOT #19		2023-06-13 11:30
MOT test	number	428532359515
Result		✓ Passed
Next expi	ry date	2024-06-14
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords	(5.2.3 (d) (i))

MOT #18	2022-05-17 08:59
MOT test number	916377803648
Result	✓ Passed

CarCheck.co.uk page 3/14



report date: 2022-08-09

**MOT #17** 2021-06-15 09:04

**MOT test number** 731550542345

**Result** ✓ Passed

Advice Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement track control arm (5.3.4 (a) (i))

Advice Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Brake pipe corroded, covered in grease or other material caliper to flexi (1.1.11 (c))

**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement track control arm (5.3.4 (a) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #16** 2019-11-16 10:33

MOT test number 486636119367

Result \rightarrow Passed

**Advice** Brake pipe corroded, covered in grease or other material osf caliper and under vehicle (chalked ) (1.1.11 (c))

Advice Suspension arm pin or bush worn but not resulting in excessive movement NSF,OSF,NSR,OSR (5.3.4 (a) (i))

**Advice** Coil spring corroded all four (5.3.1 (b) (i))

**MOT #15** 2018-11-10 09:58

**MOT test number** 104954703601

**Result** 
✓ Passed

**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

CarCheck.co.uk page 4/14



report date: 2022-08-09

MOT test number

Result

Advice Both rear adjustable tie rods have slight movement at hub ball join

Advice Brake pipe slightly damaged both centre (2.2.D.2b)

Advice Brake pipe slightly corroded centre to nearside rear (3.6.B.2c)

**MOT #13** 2017-10-16 12:02 **MOT** test number 617401274321 Result × Failed Offside Front Brake pipe seriously damaged (found during steering lock to lock check) to flexi pipe Fail (2.2.D.2b)Brake pipe slightly damaged both centre (2.2.D.2b) **Advice** Fail Offside Front Headlamp aim too low (1.8) Fail Nearside Front Brake pipe excessively corroded to flexi pipe (3.6.B.2c) Both rear adjustable tie rods have slight movement at hub ball join **Advice** Brake pipe slightly corroded centre to nearside rear (3.6.B.2c) Advice Nearside Front Headlamp aim too low (1.8) Fail

MOT #12	2016-09-24 10:50
MOT test number	257433798949
Result	<b>✓</b> Passed
MOT #11	2015-09-05 09:33
MOT test number	528391719977
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/14



report date: 2022-08-09

MOT test number

Result

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)

MOT test number

476115924207

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT test number

Result

Notice Rear brake discs are slightly corroded

Notice O/s/f tyre is wearing unevenly on inner edge

 MOT #7
 2012-07-03 17:20

 MOT test number
 136015882109

 Result
 ✓ Passed

 MOT #6
 2012-07-03 09:56

 MOT test number
 849785682100

 Result
 X Failed

 Fail
 Offside Tyre tread depth below requirements of 1.6mm (4.1.E.1)

CarCheck.co.uk page 6/14



report date: 2022-08-09

MOT #5 2011-06-24 11:49 **MOT test number** 615505071183 Result ✓ Passed MOT #4 2010-06-01 15:15 **MOT** test number 352262750174 Result ✓ Passed **MOT** #3 2010-06-01 15:15 **MOT test number** 841742750145 Result × Failed Pass with rectification Registration plate lamp not illuminating the registration plate (1.1.C.1e) Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2) **Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #2		2008-12-10 15:02
MOT test	number	993775648314
Result		✓ Passed
Notice	Slight movement in both rear suspension systems	
Notice	Front and rear discs corroded	

MOT #1	2007-07-17 12:59
MOT test number	214628697184
Result	✓ Passed

CarCheck.co.uk page 7/14



report date: 2022-08-09

### Tax & MOT check



Tax status	Valid until 1 June
Days left	36
MOT expiry date	14 June 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 8/14



report date: 2022-08-09

### Damage history

Check the damage history for this MASERATI. See if, where and when this MASERATI had damage and the car repair costs. We also check if this MASERATI was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date
Category
Type

Damage 2

Date

**Category** 

**Type** 



#### Extra MASERATI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2022-08-09

### Vehicle valuation

What is this car worth? See the vehicle value of this MASERATI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2022-08-09

## Owner history

For how long did the current and previous owner(s) have this MASERATI? How many own MASERATI have? Check it in the premium report and see all owner registrations. Downloshere.	
***************************************	
***************************************	
************	
	More info >
Plate changes  See in this check if this MASERATI had different number plates.	
Number of plates	,
Current registration	UK NIK
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2022-08-09

### Finance check

Check if this MASERATI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MASERATI has been settled.

If not, and you buy this MASERATI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MASERATI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 12/14



report date: 2022-08-09

## Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2004-03-01
Last registration	2023-06-13
Complete history	See info



2004-03-01	16 mi
2007-07-17	30.249 mi
2008-12-10	33.933 mi
2010-06-01	34.282 mi
2011-06-24	43.725 mi
2012-07-03	49.908 mi
2012-07-03	49.908 mi
2013-07-25	55.799 mi
2014-08-13	62.626 mi
2014-08-13	62.664 mi
	91.777 es
	11.777 es
	91.777 es
	11.777 es
	91.777 es
	11.777 es
	91.777 es
	11.777 es
	71,777 66
	2007-07-17 2008-12-10 2010-06-01 2011-06-24 2012-07-03 2012-07-03 2013-07-25 2014-08-13 2014-08-13

More info >

CarCheck.co.uk page 13/14



report date: 2022-08-09

		_		
luma	ncior	ור א.	MOIO	nt.
	ensior	ואט כו	WEIG	HL

Width	1822 mm
Height	1305 mm
Length	4303 mm
Wheel base	2440 mm
Kerb weight	1720 kg

## Additional information

Fuel tank capacity	88 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	80491

CarCheck.co.uk page 14/14