





report date: 2024-03-29

## General information

Make	NISSAN
Model	PATHFINDER DCI SVE
Colour	Blue
Year of manufacture	2005
Top speed	109 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	172 BHP
Max. torque	403 Nm at 2.000 rpm
Engine capacity	2.488 cc
Cylinders	4
Fuel type	Diesel
Consumption city	24.6 mpg
Consumption extra urban	37.2 mpg
Consumption combined	31.4 mpg
CO2 emission	238 g/km
CO2 label	L



CarCheck.co.uk page 1/13



SV55OFU

report date: 2024-03-29

# Internet history

## Entry 2

Date 2024-03-19

Pictures 20

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2022-02-19
Pictures	18

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-03-13
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	14
Total items failed	5

MOT #19	2024-03-14 14:43
MOT test number	681241139634
Result	✓ Passed
Next expiry date	2025-03-13

MOT #18		2022-03-08 11:33
MOT test nu	umber	588966801678
Result		<b>✓</b> Passed
Advice	Lower Vehicle heavily undersealed	
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	

MOT #17	2021-07-22 13:02
MOT test number	287649758978
Result	✓ Passed

MOT #16	2020-07-08 14:16
MOT test number	913135020301
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/13



**Pass with rectification** 

SV550FU

report date: 2024-03-29

MOT #15

MOT test number

895183937827

Result

Advice Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT test number

125497274113

Result

Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))

Advice

Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))

Fail

Nearside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))

**MOT #13** 2017-08-24 08:45 **MOT** test number 278934649213 Result ✓ Passed **MOT #12** 2016-08-23 15:03 **MOT** test number 260999191615 Result ✓ Passed 2016-08-23 15:03 **MOT #11 MOT** test number 493110987637 Result × Failed

 MOT #10
 2015-08-26 12:34

 MOT test number
 136013230364

 Result
 ✓ Passed

Nearside Stop lamp not working (1.2.1b)

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #9 2014-09-09 16:07 **MOT** test number 426082154248 Result ✓ Passed **MOT** #8 2013-09-03 09:02 **MOT** test number 279366843220 Result ✓ Passed Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Notice Nearside front outer cv boot leaking at clip Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) **Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) **Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) **Notice** Offside front outer cv boot leaking at clip

 MOT #7
 2012-09-13 15:51

 MOT test number
 719607152295

 Result
 ✓ Passed

 MOT #6
 2012-09-10 14:56

 MOT test number
 496604052266

 Result
 X Failed

 Fail

 Offside Rear coil spring incomplete (2.4.C.1a)

MOT #5

MOT test number

Result

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #4 2010-09-11 09:12

**MOT test number** 272854550235

**Result** 
✓ Passed

MOT #3 2010-09-11 09:12

MOT test number 290674750219

Result X Failed

**Pass with rectification** Offside Stop lamp adversely affected by the operation of another lamp (1.2.1f)

MOT #2 2009-09-08 10:19

**MOT test number** 824291159261

**Result** ✓ Passed

MOT #1 2008-09-11 13:17

**MOT test number** 711915358299

Result 

Passed

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/13



Tax & MOT check

Tax expired: 30 January 2022



Expires: 13 March 2025 ✓ MOT

Tax status

Days left

819 days too late

MOT expiry date

13 March 2025

Full MOT history

See MOT history

### Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



SV55OFU

report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

# Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full	
***************************************	
	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	OK SIZ
Plate since	
Current registration	NK SIE
Plate since	
	Moro info

CarCheck.co.uk page 10/13



report date: 2024-03-29

### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-09-01
Last registration	2024-03-14
Complete history	See info



Registration #1	2005-09-01	26 mi
Registration #2	2008-09-11	24.728 mi
Registration #3	2009-09-08	30.719 mi
Registration #4	2010-09-11	4.202 mi
Registration #5	2011-09-09	8.573 mi
Registration #6	2012-09-10	14.095 mi
Registration #7	2012-09-13	14.158 mi
Registration #8	2013-09-03	19.585 mi
Registration #9	2014-09-09	23.938 mi
Registration #10	2015-08-26	28.294 mi
Registration #11	2016-08-23	32.906 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.177 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditionin
50295	
50482	
50501	
50566	
50567	
50569	

$\neg$	imer		(			ᅩ
		חשו	ns 1	V 1/1/	reirei	

Width	1850 mm
Height	1783 mm
Length	4740 mm
Wheel base	2850 mm
Kerb weight	2267 kg
Max. allowed weight	2880 kg

# Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	628362

CarCheck.co.uk page 13/13