



report date: 2024-03-28

General information

Make	KIA
Model	SORENTO XE
Colour	Blue
Year of manufacture	2007
Top speed	113 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	168 BHP
Max. torque	392 Nm at 2.000 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.3 mpg
Consumption extra urban	42.2 mpg
Consumption combined	35.8 mpg
CO2 emission	209 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-06-15
Pictures	16
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-15
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	57
Total items failed	17

MOT #18	2024-01-16 18:01
MOT test number	214441998800
Result	✓ Passed
Next expiry date	2025-01-15
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Front Prop shaft joint worn, but not excessively FRONT PROP (6.1.7 (c) (i))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #17**

2024-01-15 16:29

MOT test number

504772774494

Result**✗ Failed****Advice** Nearside Front Prop shaft joint worn, but not excessively FRONT PROP (6.1.7 (c) (i))**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Rear Road wheel fixing missing (5.2.1 (a) (i))**Fail** Rear fog lamp not working (4.5.1 (a) (ii))**Fail** Nearside Front Track rod end ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Fail** Offside Front Road wheel fixing missing (5.2.1 (a) (i))**Fail** Oil leaking excessively from engine (8.4.1 (a) (i))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))**Fail** Offside Front Direction indicator not working (4.4.1 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #16**

2022-11-19 13:57

MOT test number

977127106325

Result

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #15

2021-10-06 15:31

MOT test number

254408800685

Result

✓ Passed

- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14

2021-10-06 15:31

MOT test number

978115330289

Result

✗ Failed

- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Pass with rectification** Front Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

**MOT #13**

2020-08-17 13:29

MOT test number

941977217982

Result

✓ Passed

Advice Nearside Rear Brake pipe corroded, covered in grease or other material X2 (1.1.11 (c))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material X2 (1.1.11 (c))**Minor** Nearside Obligatory mirror slightly damaged (3.3 (b) (i))**MOT #12**

2020-08-17 08:29

MOT test number

427038072908

Result

✗ Failed

Advice Offside Rear Brake pipe corroded, covered in grease or other material X2 (1.1.11 (c))**Minor** Nearside Obligatory mirror slightly damaged (3.3 (b) (i))**Fail** Rear fog lamp not working (4.5.1 (a) (ii))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material X2 (1.1.11 (c))**Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))



MOT #11	2019-08-14 15:18
MOT test number	102628708022
Result	✓ Passed
Advice	Nearside Front Anti-lock braking system wiring damaged but not excessively (1.6 (d))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material x2 (1.1.11 (c))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front exhaust flexi deteriorated
Advice	Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Anti-lock braking system wiring damaged but not excessively (1.6 (d))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material x2 (1.1.11 (c))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10**

2019-08-14 10:41

MOT test number

200435905121

Result**✗ Failed**

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Nearside Front Anti-lock braking system wiring damaged but not excessively (1.6 (d))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material x2 (1.1.11 (c))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))
- Fail** Offside Front Drive shaft joint constant velocity boot missing (6.1.7 (g) (ii))
- Advice** Front exhaust flexi deteriorated
- Advice** Offside Front Anti-lock braking system wiring damaged but not excessively (1.6 (d))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material x2 (1.1.11 (c))

MOT #9

2018-08-09 09:49

MOT test number

858555643571

Result**✓ Passed**

- Advice** Offside Front Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))



MOT #8	2017-08-17 12:03
MOT test number	383098410820
Result	✓ Passed
MOT #7	2016-08-11 09:26
MOT test number	646290310355
Result	✓ Passed
MOT #6	2015-07-29 12:41
MOT test number	564402544086
Result	✓ Passed
MOT #5	2015-01-30 14:45
MOT test number	639380935060
Result	✓ Passed
MOT #4	2014-02-07 13:07
MOT test number	458278134088
Result	✓ Passed
MOT #3	2013-01-30 12:24
MOT test number	787390333001
Result	✓ Passed
MOT #2	2012-01-30 14:17
MOT test number	736860632043
Result	✓ Passed
MOT #1	2010-11-26 11:46
MOT test number	404620830416
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
15 January 2025

Tax status	Valid until 1 August
Days left	93
MOT expiry date	15 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	EN57BZT
Plate since	2019-03-28
Current registration	EN57BZT
Plate since	2019-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-12-19
Last registration	2024-01-16
Complete history	See info



Registration #1	2007-12-19	25 mi
Registration #2	2010-11-26	18.926 mi
Registration #3	2012-01-30	28.497 mi
Registration #4	2013-01-30	37.728 mi
Registration #5	2014-02-07	45.532 mi
Registration #6	2015-01-30	59.346 mi
Registration #7	2015-07-29	64.220 mi
Registration #8	2016-08-11	77.994 mi
Registration #9	2017-08-17	91.845 mi
Registration #10	2018-08-09	104.262 mi
Registration #11	2019-08-09	104.262 mi
Registration #12	2020-08-09	104.262 mi
Registration #13	2021-08-09	104.262 mi
Registration #14	2022-08-09	104.262 mi
Registration #15	2023-08-09	104.262 mi
Registration #16	2024-01-16	104.262 mi
Registration #17	2024-01-16	104.262 mi
Registration #18	2024-01-16	104.262 mi
Registration #19	2024-01-16	104.262 mi
Registration #20	2024-01-16	104.262 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1885 mm
Height	1805 mm
Length	4590 mm
Wheel base	2710 mm
Kerb weight	2065 kg
Max. allowed weight	2640 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4CB7243232