





report date: 2024-03-28

General information

Make	MINI
Model	JOHN COOPER WORKS COOPER S
Colour	Grey
Year of manufacture	2017
Top speed	145 mph
0 - 60 mph	6.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	192 BHP
Max. torque	280 Nm at 1.250 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	41.5 mpg
Consumption extra urban	64.2 mpg
Consumption combined	54.3 mpg
CO2 emission	126 g/km
CO2 label	D



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

_		•		_	-
-	n	т	rv	,	

EIIII y I	
Date	2021-10-04
Pictures	0
Listing price	View report

source: heycar.co.uk

CarCheck.co.uk page 2/11



MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2024-08-21
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	12
Total items failed	2

MOT #6	2023-08-03 07:56
MOT test number	237059873668
Result	✓ Passed
Next expiry date	2024-08-21

MOT #5		2022-08-22 13:41
MOT test	number	159301702053
Result		✓ Passed
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Nail in tyre	
Advice Nearside Front Tyre worn close to legal limit/worn on edge 2.5mm (5.2.3 (e))		
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.	1.14 (a) (ii))

CarCheck.co.uk page 3/11



MOT #4 2022-08-22 10:08

MOT test number 482341879147

Result X Failed

Fail Offside Front Tyre has a bulge, caused by separation or partial failure of its structure outer sidewall (5.2.3 (d) (ii))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 2.5mm (5.2.3 (e))

Advice Offside Rear Nail in tyre

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #3 2021-05-24 10:31

MOT test number 981171204290

Result ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge on 2-3mm (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge on 2-3mm (5.2.3 (e))

MOT #2 2021-05-21 14:10

MOT test number 216308959498

Result × Failed

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

Advice Offside Front Tyre worn close to legal limit/worn on edge on 2-3mm (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge on 2-3mm (5.2.3 (e))

MOT #1 2020-09-05 09:13

MOT test number 429609487120

Result ✓ Passed

CarCheck.co.uk page 4/11



Tax & MOT check





Expires: 21 August 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	21 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

PX67WKC

report date: 2024-03-28

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI Check it in the premium report and see all owner registrations. Download the full report <u>here</u> .	have?
THE PARTY OF THE P	

THE STATE OF THE S	

Plate changes

More info >

More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-09-29
Last registration	2023-08-03
Complete history	See info



Registration #1	2017-09-29	18 mi
Registration #2	2020-09-05	26.670 mi
Registration #3	2021-05-21	30.152 mi
Registration #4	2021-05-24	30.160 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		n.m.

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	79%
Children	73%
Pedestrian	66%
Safety systems	56%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	1727 mm
Height	1414 mm
Length	3850 mm
Wheel base	2495 mm
Kerb weight	1250 kg
Max. allowed weight	1655 kg

Additional information

Fuel tank capacity	44
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 11/11