





report date: 2024-03-28

General information

Make	MAZDA
Model	BONGO
Colour	White
Year of manufacture	1997
Gearbox	-

Engine & fuel consumption

Engine capacity	2.490 cc
Fuel type	Diesel



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history


Entry 1

Date 2021-06-16

Pictures 13

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



R87ATR report date: 2024-03-28

MOT history

MOT expiry date	2023-04-29
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	27
Total items failed	9

MOT #17		2022-04-27 10:27
MOT test	number	738151175734
Result		✓ Passed
Next expi	y date	2023-04-29
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice	Both side inner sills have holes in. not within 30 cm of componant mountings	

MOT #16	2021-04-	30 08:06
MOT test	number 73149	1354384
Result		/ Passed
Advice	Hole caused by corrosion offside front inner sill	
Advice	Hole caused by corrosion nearside centre inner sill	
Advice (a) (ii))	Front Brake disc worn, pitted or scored, but not seriously weakened Heavily on inner faces	(1.1.14
Advice	Hole caused by corrosion nearside front inner sill	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #15 2021-04-27 12:34

MOT test number 170235761451

Result X Failed

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Hole caused by corrosion nearside front inner sill

Fail Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Hole caused by corrosion offside front inner sill

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Hole caused by corrosion nearside centre inner sill

Fail Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Inner and outer sills within 30cm of suspension mounting (5.3.6 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Heavily on inner faces (1.1.14 (a) (ii))

MOT #14 2019-06-06 10:18

MOT test number 324751272191

Result

Passed

Advice Brake disc worn, pitted or scored, but not seriously weakened All round (1.1.14 (a) (ii))

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

MOT #13 2018-05-11 09:50

MOT test number 591063742690

Result

Passed

Advice Nearside Front Inner brake disc worn, pitted or scored, but not seriously weakened surface (3.5.1i)

Advice Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened surface (3.5.1i)

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #12

MOT test number

964345503076

Result

Advice Front brake discs corroded

Advice Sills corroded

MOT #11 2017-04-03 14:09 **MOT** test number 186339682299 Result × Failed Fail Nearside Front Lower Suspension arm ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2) Sills corroded Advice Offside Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents Fail the ingress of dirt etc (2.5.C.1a) Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2) Fail **Advice** Front brake discs corroded

MOT #10

MOT test number

366336278833

Result

Advice

Parking brake lever has little reserve travel (3.1.6b)

Advice

Offside Front brake disc worn, pitted or scored, but not seriously weakened inner face (3.5.1i)

Advice

Nearside Front brake disc worn, pitted or scored, but not seriously weakened inner face (3.5.1i)

MOT #9

MOT test number

S17308704324

Result

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 5/12



report date: 2024-03-28

MOT #8 2013-11-05 12:38

MOT test number 247999403362

Result ✓ Passed

MOT #7 2013-11-01 10:47

MOT test number 856385203392

Result X Failed

Fail Offside Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #6 2012-11-05 12:24

MOT test number 248560312359

Result ✓ Passed

MOT #5 2011-11-16 12:42

MOT test number 889050321390

MOT #4 2010-09-27 12:56

MOT test number 710560570250

Result
✓ Passed

MOT #3 2009-09-22 17:02

MOT test number 584975469285

Result
✓ Passed

MOT #2 2008-09-12 14:39

MOT test number 644586458253

Advice Nearside Rear Anti-roll bar rubber mounting deteriorated but not resulting in excessive movement

(2.4.G.2)

Notice Long travel parking brake

CarCheck.co.uk page 6/12



report date: 2024-03-28

MOT test number

433806758240

Result

Notice Long travel parking brake

Advice (2.4.G.2)

Pass with rectification (2.5.C.1a)

Notice Long travel parking brake

CarCheck.co.uk page 7/12



report date: 2024-03-28

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full research	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	SIK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



R87ATR report date: 2024-03-28

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-09-12
Last registration	2022-04-27
Complete history	See info



Registration #1	2008-09-12	67.352 mi
Registration #2	2009-09-22	113.106 mi
Registration #3	2010-09-27	115.588 mi
Registration #4	2011-11-16	117.654 mi
Registration #5	2012-11-05	120.179 mi
Registration #6	2013-11-01	124.197 mi
Registration #7	2013-11-05	124.201 mi
Registration #8	2014-11-04	127.408 mi
Registration #9	2016-03-31	128.522 mi
Registration #10		11.777 au
Registration #11		11.177 es
Registration #11 Registration #12		1.77 44
		11.77 mi 11.77 mi 11.77 mi
Registration #12		11.777 ea 11.777 ea 11.777 ea
Registration #12 Registration #13		11.777 es 11.777 es 11.777 es 11.777 es
Registration #12 Registration #13 Registration #14		11.777 es 11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Additional information

Number of seats	8
Engine number	N/K

CarCheck.co.uk page 12/12