





report date: 2024-03-28

## General information

Make	PEUGEOT
Model	107 ACCESS
Colour	Grey
Year of manufacture	2012
Top speed	99 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/12



# Internet history

## Entry 1

Date 2021-10-09

Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



### MOT history

MOT expiry date	2024-08-26
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	11
Total items failed	8

MOT #13	2023-08-21 14:56
MOT test number	881281958673
Result	<b>✓</b> Passed
Next expiry date	2024-08-26

MOT #12 2023-08-15 11:52

**MOT test number** 694880811528

Result

× Failed

**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Nearside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))

 MOT #11
 2022-08-24 11:12

 MOT test number
 713882126055

 Result
 ✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

 MOT #10
 2021-08-27 08:41

 MOT test number
 373658446929

 Result
 ✓ Passed

CarCheck.co.uk page 3/12



Result

CV12YLJ report date: 2024-03-28

Passed

MOT #9 2021-08-24 15:42

MOT test number 350574044624

**Result** X Failed

Fail Nearside Front Anti-roll bar linkage pin or bush excessively worn stabilizer link (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Anti-roll bar linkage pin or bush excessively worn stabilizer link (5.3.4 (a) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8 2020-08-05 12:13

MOT test number 156552312482

Result 

Passed

Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

MOT #7 2020-03-12 12:43

MOT test number 232497507537

Advice Parking permit on nearside of windscreen, but not significantly affecting drivers view

MOT #6 2020-03-12 12:43

MOT test number 431178169264

Result × Failed

Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Parking permit on nearside of windscreen, but not significantly affecting drivers view

**Pass with rectification** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #5 2019-03-28 10:51

**MOT test number** 637372674728

**Result** ✓ Passed

CarCheck.co.uk page 4/12



MOT test number

Result

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3

MOT test number

Result

Advice Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)

MOT #2

MOT test number

Result

Advice Both rear tyres cracking in the tread

2016-03-31 09:40

997379665379

✓ Passed

 MOT #1
 2015-04-03 10:43

 MOT test number
 897803695061

 Result
 ✓ Passed

CarCheck.co.uk page 5/12



# Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	26 August 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Vehicle Class	40
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



O	بمرحط ماحا
UMMAR	nistary
Owner	IIIJUU Y

e when moterly	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
********	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	OK SIE SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-05-16
Last registration	2023-08-21
Complete history	See info



Registration #1	2012-05-16	6 mi
Registration #2	2015-04-03	15.629 mi
Registration #3	2016-03-31	23.833 mi
Registration #4	2017-03-18	41.988 mi
Registration #5	2018-04-03	58.463 mi
Registration #6	2019-03-28	74.428 mi
Registration #7	2020-03-12	87.919 mi
Registration #8	2020-03-12	87.919 mi
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		9.777 es
Registration #12		11.777 es
Registration #13		9.777 es
Registration #14		11.777 es
Registration #15		11,117 es

More info >

CarCheck.co.uk page 11/12



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
S0567	
50569	

# Safety ratings

# Dimensions & weight

Width	1630 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	900 kg
Max. allowed weight	1180 kg

## Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	7155098

CarCheck.co.uk page 12/12