





report date: 2024-03-29

## General information

| Make                | MERCEDES          |
|---------------------|-------------------|
| Model               | CLS CLS320 CDI    |
| Colour              | Silver            |
| Year of manufacture | 2007              |
| Top speed           | 148 mph           |
| 0 - 60 mph          | 7.0 seconds       |
| Gearbox             | 7 speed automatic |

## Engine & fuel consumption

| Power                   | 221 BHP             |
|-------------------------|---------------------|
| Max. torque             | 510 Nm at 2.800 rpm |
| Engine capacity         | 2.987 сс            |
| Cylinders               | 6                   |
| Fuel type               | Diesel              |
| Consumption city        | 27.2 mpg            |
| Consumption extra urban | 47.9 mpg            |
| Consumption combined    | 27.7 mpg            |
| CO2 emission            | 200 g/km            |
| CO2 label               | J                   |



CarCheck.co.uk page 1/13



P100NKX report date: 2024-03-29

## Internet history

### Entry 2

Date 2021-07-16

Pictures 2

Listing price <u>View report</u>





source: cargurus.co.uk

### Entry 1

| Date     | 2021-07-15 |
|----------|------------|
| Pictures | 2          |

Listing price <u>View report</u>





source: autotrader.co.uk

CarCheck.co.uk page 2/13



P100NKX report date: 2024-03-29

MOT history

| MOT expiry date    | 2024-09-08 |
|--------------------|------------|
| MOT pass rate      | 83 %       |
| MOT passed         | 15         |
| Failed MOT tests   | 3          |
| Total advice items | 22         |
| Total items failed | 4          |

| MOT #18  | 2023-08-23 11:53 |
|--|------------------|
| MOT test number  | 268699206633     |
| Result   | ✓ Passed         |
| Next expiry date   | 2024-09-08       |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge nearing wear bars (5.2.3 | 3 (e))           |

| MOT #17  |  | 2022-09-05 13:23  |
|----------|--|-------------------|
| MOT test | number   | 350677602169      |
| Result   |  | ✓ Passed          |
| Advice   | Nearside Rear Tyre worn close to legal limit/worn on edge nearing wear bars (5.2.  | 3 (e))            |
| Advice   | Offside Front Tyre has a cut but not deep enough to reach the ply or cords in trea | d (5.2.3 (d) (i)) |
| Advice   | Offside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))                  |                   |
| Advice   | Offside Rear Tyre has a cut but not deep enough to reach the ply or cords in treac | d (5.2.3 (d) (i)) |

| MOT #16         | 2021-09-09 15:47 |
|-----------------|------------------|
| MOT test number | 931258549424     |
| Result          | <b>✓</b> Passed  |

CarCheck.co.uk page 3/13



Result

P100NKX

report date: 2024-03-29

Passed

**MOT #15** 2021-09-09 15:47

**MOT test number** 688648829726

**Result** X Failed

Pass with rectification Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #14** 2020-10-29 11:39

MOT test number 550513550306

**MOT #13** 2019-11-11 10:20

MOT test number 654857679830

Advice Central Rear Exhaust silencer slightly loose (8.1.1 (b) (i))

**MOT #12** 2018-11-15 13:41

MOT test number 166696719807

**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #11** 2018-11-08 17:20

MOT test number 275740236130

Result × Failed

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/13



report date: 2024-03-29

**MOT #10** 2017-11-16 11:29

**MOT test number** 600101534905

**Result** ✓ Passed

**Advice** Rear brake pipes starting to corrode

**Advice** No emissions detected

**Advice** Nearside Front Tyre perished

MOT #9 2016-11-16 13:10

MOT test number 484440754189

**Result** ✓ Passed

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Front Play in steering rack inner joint(s)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Front Upper Suspension arm has slight play in a ball joint (2.4.G.2)

MOT #8 2015-10-08 15:05

**MOT test number** 190487733325

MOT #7 2014-10-06 11:04

**MOT test number** 845409674227

Result \rightarrow Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

| MOT #6   |   | 2013-10-11 09:20 |
|----------|---|------------------|
| MOT test | number  | 166664083235     |
| Result   |   | ✓ Passed         |
| Advice   | Offside Rear Tyre worn close to the legal limit (4.1.E.1)   |                  |
| Advice   | Offside Front Tyre worn close to the legal limit (4.1.E.1)  |                  |
| Advice   | Nearside Rear Tyre worn close to the legal limit (4.1.E.1)  |                  |
| Advice   | Nearside Front Tyre worn close to the legal limit (4.1.E.1) |                  |

| MOT #5   | 2012-10-09 11:44 |
|--|------------------|
| MOT test number                                    | 306013482463     |
| Result   | ✓ Passed         |
|  |                  |
| MOT #4   | 2011-10-11 15:08 |
| MOT test number                                    | 166834381242     |
| Result   | <b>✓</b> Passed  |
|  |                  |
| MOT #3   | 2011-10-05 17:14 |
| MOT test number                                    | 809488471238     |
| Result   | <b>X</b> Failed  |
| Fail Offside Front Road wheel distorted (4.2.A.1a) |                  |

| MOT #2          | 2010-10-14 09:03 |
|-----------------|------------------|
| MOT test number | 702967080278     |
| Result          | ✓ Passed         |

| MOT #1   | 2010-04-20 14:59 |
|--|------------------|
| MOT test number  | 223880310492     |
| Result   | <b>✓</b> Passed  |
| Advice Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a) |                  |

CarCheck.co.uk page 6/13



P100NKX report date: 2024-03-29

Tax & MOT check





**Expires:** 8 September 2024

| Tax status       | Valid until 1 September |
|------------------|-------------------------|
| Days left        | 124                     |
| MOT expiry date  | 8 September 2024        |
| Full MOT history | See MOT history         |

### Tax calculation

| Vehicle class                           | 49         |
|---|------------|
| Band                                    | J          |
| Single payment (12 months)              | £ 365,00,- |
| Single six month payment                | £ 200,75,- |
| Total payable by 12 monthly instalments | £ 383,25,- |

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1

| Date     |  |
|----------|--|
| Category |  |
| Type     |  |

#### Damage 2

| Category   |  |
|------------|--|
| Date       |  |
| Dailiage 2 |  |





#### Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



P100NKX report date: 2024-03-29

| For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report here.  More info >  Plate changes  See in this check if this MERCEDES had different number plates. | Owner history   |             |
|--|---|-------------|
| See in this check if this MERCEDES had different number plates.  | MERCEDES have? Check it in the premium report and see all owner registrations. Download |             |
| See in this check if this MERCEDES had different number plates.  | *********   |             |
| See in this check if this MERCEDES had different number plates.  |   |             |
| See in this check if this MERCEDES had different number plates.  | ***************************************   |             |
| See in this check if this MERCEDES had different number plates.  |   |             |
| See in this check if this MERCEDES had different number plates.  |   |             |
| See in this check if this MERCEDES had different number plates.  | ***************************************   |             |
| See in this check if this MERCEDES had different number plates.  | Plate changes   | More info > |
|  |   |             |
|  | Number of plates  | ,           |
| Plate since  | Current registration  | NK NY       |
| Plate since  | Plate since   |             |
|  | Current registration  | UK ZIK      |
| More info >  | Flate since   |             |
|  |   | More info > |
|  |   |             |

CarCheck.co.uk page 10/13



report date: 2024-03-29

### Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| 0.1.116           |  |

**Contact info** 

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

## Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 21         |
| First mileage registration | 2007-03-01 |
| Last registration          | 2023-08-23 |
| Complete history           | See info   |



| Registration #1                   | 2007-03-01 | 24 mi      |
|-----------------------------------|------------|------------|
| Registration #2                   | 2010-04-20 | 37.710 mi  |
| Registration #3                   | 2010-10-14 | 39.134 mi  |
| Registration #4                   | 2011-10-05 | 47.927 mi  |
| Registration #5                   | 2011-10-11 | 48.037 mi  |
| Registration #6                   | 2012-10-09 | 56.826 mi  |
| Registration #7                   | 2013-10-11 | 64.306 mi  |
| Registration #8                   | 2014-10-06 | 70.408 mi  |
| Registration #9                   | 2015-10-08 | 76.773 mi  |
| Registration #10                  | 2016-11-16 | 81.151 mi  |
| Registration #11                  | 2017-11-16 | 85.904 mi  |
| Registration #12                  |            | 71.777 es  |
| Registration #13                  |            | 77.777 66  |
| Registration #14                  |            | 77.777 es  |
| Registration #15                  |            | 77.777 66  |
| Registration #16                  |            | 77,777 44  |
| Registration #17                  |            | 77.777 66  |
| Registration #18                  |            | 00 DOT 444 |
|                                   |            |            |
| Registration #19                  |            | 11.777 es  |
| Registration #19 Registration #20 |            | 11.777 ea  |

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

## Safety ratings

| NCAP rating | ****            |
|-------------|-----------------|
| Video       | see crash video |



# Dimensions & weight

| Width       | 2059 mm |
|-------------|---------|
| Height      | 1403 mm |
| Length      | 4913 mm |
| Wheel base  | 2854 mm |
| Kerb weight | 1815 kg |

## Additional information

| · · · · · · · · · · · · · · · · · · · |                  |
|---------------------------------------|------------------|
| Fuel tank capacity                    | 80 I             |
| Fuel delivery                         | Direct Injection |
| Number of doors                       | 4                |
| Number of seats                       | 4                |
| Number of axles                       | 2                |
| Engine number                         | 64292040446156   |

CarCheck.co.uk page 13/13