





report date: 2024-03-28

General information

Make	HYUNDAI	
Model	SANTA FE CRDI PREMIUM	
Colour	Blue	
Year of manufacture	2012	
Top speed	118 mph	
0 - 60 mph	9.8 seconds	
Gearbox	6 speed Manual	

Engine & fuel consumption

Power	194 BHP
Max. torque	422 Nm at 2.500 rpm
Engine capacity	2.199 сс
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/13



Internet history

Entry 3

Date 2022-11-14

Pictures 0

Listing price View report

source: carcraft.co.uk

Entry 2

Date 2022-05-06

Pictures 10

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-09-14

Pictures 9

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-12-10
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	18
Total items failed	7

MOT #13	2023-12-11 09:01
MOT test number	989244771250
Result	✓ Passed
Next expiry date	2024-12-10
Advice Nearside Front Daytime running lamp inoperative Advice Tow Bar corroded	

MOT #12	2023-11-02 08:59
MOT test number	148858442617
Result	X Failed
Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))	
Fail Windscreen washer jets misaligned and not providing sufficient fluid to the windsc	creen (3.5 (a))
Fail Offside Front Lower Suspension arm ball joint dust cover no longer prevents the in (b) (ii))	ngress of dirt (5.3.4
Minor Front Position lamp incorrect colour not matched colours (4.2.3 (a) (i))	
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail Power steering malfunctioning (2.1.5 (a))	
Fail Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))	

CarCheck.co.uk page 3/13



MOT #11 2022-11-18 17:07 **MOT test number** 364671775381 Result ✓ Passed MOT #10 2022-04-28 15:19 **MOT** test number 925560594447 Result ✓ Passed MOT #9 2021-05-25 14:12 **MOT test number** 916303156419 Result ✓ Passed **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8	2021-05-25 10:22
MOT test number	773780638122
Result	X Failed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt	

CarCheck.co.uk page 4/13



MOT #7 2020-05-27 10:01

MOT test number 811388221228

Result ✓ Passed

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #6 2019-05-16 09:01

MOT test number 823756093782

Result ✓ Passed

Advice Nearside Front Tyre slightly damaged/cracking or perishing tread (5.2.3 (d) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing tread (5.2.3 (d) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #5 2018-05-22 13:13

MOT test number 998261114782

Result ✓ Passed

MOT #4 2018-05-22 13:13

MOT test number 436054751409

Result X Failed

Pass with rectification Front Tyre tread depth below requirements of 1.6mm both front tyres (5.2.3 (e))

MOT #3 2017-11-13 11:38

MOT test number 104178148943

Result
✓ Passed

Advice Brake master cylinder was low. Brake fluid added to max level.

Advice Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 5/13



MOT #2	2016-11-09 11:42
MOT test number	175521838099
Result	✓ Passed
MOT #1	2015-11-13 11:44
MOT test number	724061567219
Result	✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	10 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of sistes	
Current registration	NE NE
Plate since	
Current registration	NK.
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-11-13
Last registration	2023-12-11
Complete history	See info



Registration #1	2012-11-13	13 mi
Registration #2	2015-11-13	36.823 mi
Registration #3	2016-11-09	48.295 mi
Registration #4	2017-11-13	66.721 mi
Registration #5	2018-05-22	69.292 mi
Registration #6	2018-05-22	69.292 mi
Registration #7	2019-05-16	73.098 mi
Registration #8	2020-05-27	78.233 mi
Registration #9	2021-05-25	85.486 mi
Registration #10		71.777 es
Registration #11		
Registration #12		0.07 m
Registration #12 Registration #13		11.77 m
		11.77 m
Registration #13		11.777 es 11.777 es 11.777 es
Registration #13 Registration #14		11.777 es 11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1880 mm
Height	1690 mm
Length	4690 mm
Wheel base	2700 mm
Kerb weight	1963 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	64
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/1.

Number of axles 2

Engine number D4HBCU678291