



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN TDI SE 5STR
Colour	Black
Year of manufacture	2009
Top speed	110 mph
0 - 60 mph	13.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	156 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-26
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-09-06
MOT pass rate	60 %
MOT passed	12
Failed MOT tests	8
Total advice items	34
Total items failed	14

MOT #20	2023-08-17 13:44
MOT test number	820461344291
Result	✓ Passed
Next expiry date	2024-09-06
Minor	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #19	2023-08-17 09:24
MOT test number	275643489358
Result	✗ Failed
Fail	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #18** 2022-09-06 08:35**MOT test number** 744597763354**Result** ✓ Passed**Minor** Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #17** 2021-09-07 11:21**MOT test number** 648793576625**Result** ✓ Passed**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**MOT #16** 2021-09-07 09:19**MOT test number** 676680232680**Result** ✗ Failed**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Rear Tyre has ply or cords exposed inner edge (5.2.3 (d) (ii))**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Fail** Nearside Rear Tyre has ply or cords exposed inner edge (5.2.3 (d) (ii))**MOT #15** 2020-10-06 14:15**MOT test number** 525130452386**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #14**

2020-10-05 09:11

MOT test number

489650040583

Result

✗ Failed

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Side repeater light intensity significantly reduced (4.4.3 (a))**MOT #13**

2019-10-11 10:08

MOT test number

553688092398

Result

✓ Passed

Advice Offside Rear brake disc slightly corroded**Advice** Slight rear brake imbalance, offside lower**MOT #12**

2019-10-10 09:18

MOT test number

161649852530

Result

✗ Failed

Fail Offside Front Upper Macpherson strut mounting damaged and seriously weakened (5.3.3 (b) (i))**Advice** Slight rear brake imbalance, offside lower**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Rear brake disc slightly corroded**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #11**

2018-07-31 15:26

MOT test number

203133242464

Result

✓ Passed

**MOT #10** 2018-07-31 15:26**MOT test number** 578754637282**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))**MOT #9** 2017-09-13 08:31**MOT test number** 789804355515**Result** ✓ Passed**Advice** Both front tyres wearing inner edge**MOT #8** 2017-09-11 09:42**MOT test number** 479588186802**Result** ✗ Failed**Fail** Central Rear Stop lamp not working (1.2.1b)**Advice** Both front tyres wearing inner edge**MOT #7** 2016-09-14 14:17**MOT test number** 674273931277**Result** ✓ Passed**Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)**Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)

**MOT #6**

2016-09-14 14:17

MOT test number

207879629150

Result**✗ Failed****Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)**Pass with rectification** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)**Pass with rectification** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #5**

2015-09-17 13:44

MOT test number

979782462194

Result**✓ Passed****Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #4**

2014-09-11 11:05

MOT test number

519594554272

Result**✓ Passed****Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3**

2014-09-11 11:05

MOT test number

867484554205

Result**✗ Failed****Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2013-09-17 13:31
MOT test number	155010263241
Result	✓ Passed
Advice	Nearside Rear coil spring worn (2.4.C.1b)
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #1	2012-09-18 12:39
MOT test number	307292862489
Result	✓ Passed
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)
Notice	Child seat fitted not allowing full inspection of adult belt



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
6 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	6 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 VK59TWL
Plate since	2019-03-29
Current registration	 VK59TWL
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-10-23
Last registration	2023-08-17
Complete history	See info



Registration #1	2009-10-23	17 mi
Registration #2	2012-09-18	19.022 mi
Registration #3	2013-09-17	22.553 mi
Registration #4	2014-09-11	26.152 mi
Registration #5	2015-09-17	30.670 mi
Registration #6	2016-09-14	35.234 mi
Registration #7	2016-09-14	35.234 mi
Registration #8	2017-09-11	38.966 mi
Registration #9	2017-09-13	39.007 mi
Registration #10	2018-07-31	42.806 mi
Registration #11	2018-07-31	42.806 mi
Registration #12	2019-05-29	45.557 mi
Registration #13	2019-05-29	45.557 mi
Registration #14	2019-05-29	45.557 mi
Registration #15	2019-05-29	45.557 mi
Registration #16	2019-05-29	45.557 mi
Registration #17	2019-05-29	45.557 mi
Registration #18	2019-05-29	45.557 mi
Registration #19	2019-05-29	45.557 mi
Registration #20	2019-05-29	45.557 mi
Registration #21	2019-05-29	45.557 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1498 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Engine number	BXE 733752