



report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA EXCLUSIV CDTI
Colour	Grey
Year of manufacture	2013
Top speed	117 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	175 g/km
CO2 label	H





Internet history

Entry 2

Date	2023-06-15
Pictures	15
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-11-05
Pictures	21
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-08
MOT pass rate	57 %
MOT passed	8
Failed MOT tests	6
Total advice items	51
Total items failed	5

MOT #14	2023-06-09 13:42
MOT test number	533020096152
Result	✓ Passed
Next expiry date	2024-06-08

MOT #13	2022-10-05 13:02
MOT test number	198134202808
Result	✓ Passed

- Advice** Oil leak, but not excessive gearbox oil leaking. (8.4.1 (a) (i))
- Advice** Nearside Rear lamp assembly condensated.
- Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

**MOT #12**

2022-09-29 11:12

MOT test number

566877821754

Result**✗ Failed**

- MAJOR** Reversing lamp inoperative (4.6.1 (a))
- MAJOR** Central Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Rear lamp assembly condensated.
- MAJOR** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
- Advice** Oil leak, but not excessive gearbox oil leaking. (8.4.1 (a) (i))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #11

2021-09-15 14:00

MOT test number

495421232787

Result**✓ Passed**

- Advice** Under trays fitted
- Advice** Front Shock absorbers has light misting of oil both (5.3.2 (b))

MOT #10

2021-09-15 09:20

MOT test number

832175338934

Result**✗ Failed**

- Advice** Under trays fitted
- DANGEROUS** Rear Brake disc in such a condition that it is seriously weakened both (1.1.14 (a) (ii))
- Advice** Front Shock absorbers has light misting of oil both (5.3.2 (b))
- DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick both (1.1.13 (a) (ii))

**MOT #9** 2020-09-26 15:35**MOT test number** 259506067448**Result** ✓ Passed

- Advice** Stop lamp(s) non-obligatory stop lamp not working High Level brake light not working (4.3.1 (a) (ii))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Slight play in seat runner
- Advice** Oil leak, but not excessive Engine Sump (8.4.1 (a) (i))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #8 2020-09-26 11:01**MOT test number** 119892896010**Result** ✗ Failed

- MAJOR** Nearside Front Suspension arm pin or bush excessively worn Rear bush (5.3.4 (a) (i))
- Advice** Stop lamp(s) non-obligatory stop lamp not working High Level brake light not working (4.3.1 (a) (ii))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- MAJOR** Offside Front Lower Suspension arm pin or bush excessively worn Rear bush (5.3.4 (a) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Oil leak, but not excessive Engine Sump (8.4.1 (a) (i))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Slight play in seat runner

**MOT #7**

2019-09-24 13:01

MOT test number

385091412393

Result

✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Coolant leak
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6

2019-09-24 11:41

MOT test number

483260972913

Result

✗ Failed

- Advice** Coolant leak
- MAJOR** Battery insecure and likely to cause a short circuit (4.13 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Child Seat fitted not allowing full inspection of adult belt
- MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5

2018-09-26 11:05

MOT test number

853074061455

Result

✓ Passed

- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #4** 2018-09-26 09:30**MOT test number** 698109667635**Result** ✗ Failed**MAJOR** Offside Front Position lamp not working (4.2.1 (a))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Reversing lamp inoperative (4.6.1 (a))**MOT #3** 2017-09-27 08:46**MOT test number** 182747700787**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**MOT #2** 2017-09-27 08:46**MOT test number** 486067847882**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Offside Headlamp aim too low (1.8)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Pass with rectification** Nearside Headlamp aim too low (1.8)



MOT #1	2016-09-26 07:53
MOT test number	846317400625
Result	✓ Passed
Advice	Front Shock absorber has a light misting of oil both sides (2.7.3)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
8 June 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	8 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history


Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	BK63VLR
Plate since	2019-06-29
Current registration	BK63VLR
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2013-09-30
Last registration	2023-06-09
Complete history	See info



Registration #1	2013-09-30	25 mi
Registration #2	2016-09-26	41.632 mi
Registration #3	2017-09-27	57.567 mi
Registration #4	2017-09-27	57.567 mi
Registration #5	2018-09-26	68.187 mi
Registration #6	2018-09-26	68.187 mi
Registration #7	2019-09-24	79.930 mi
Registration #8	2019-09-24	79.930 mi
Registration #9	2020-09-26	88.840 mi
Registration #10	2023-06-09	170.000 mi
Registration #11	2023-06-09	170.000 mi
Registration #12	2023-06-09	170.000 mi
Registration #13	2023-06-09	170.000 mi
Registration #14	2023-06-09	170.000 mi
Registration #15	2023-06-09	170.000 mi
Registration #16	2023-06-09	170.000 mi
Registration #17	2023-06-09	170.000 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1836 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	115515K