



report date: 2024-03-28

General information

Make	FIAT
Model	500X MULTIAIR POP STAR
Colour	Bronze
Year of manufacture	2016
Top speed	118 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-04-11
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	8
Total items failed	5

MOT #9	2024-04-11 13:05
MOT test number	253192796376
Result	✓ Passed
Next expiry date	2025-04-11

MOT #8	2024-04-11 13:05
MOT test number	558915872769
Result	✗ Failed
Pass with rectification Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	

MOT #7	2023-04-04 10:48
MOT test number	704816728209
Result	✓ Passed

MOT #6	2022-04-05 11:52
MOT test number	105714405270
Result	✓ Passed

MOT #5	2021-04-12 14:12
MOT test number	240579834884
Result	✓ Passed

**MOT #4** 2021-04-12 11:22**MOT test number** 805645536622**Result** ✗ Failed

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #3 2020-03-11 10:40**MOT test number** 958590156741**Result** ✓ Passed

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords small cuts on inner side wall (5.2.3 (d) (i))

Advice Nearside Front Door mirror damaged, glass smashed, indicator water, cracked cover

Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords small cuts on inner side wall (5.2.3 (d) (i))

MOT #2 2020-03-11 09:24**MOT test number** 874517488107**Result** ✗ Failed

Advice Nearside Front Door mirror damaged, glass smashed, indicator water, cracked cover

Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords small cuts on inner side wall (5.2.3 (d) (i))

Fail Nearside Rear Tyre has ply or cords exposed Bulged out of shape. DO NOT DRIVE (5.2.3 (d) (ii))

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords small cuts on inner side wall (5.2.3 (d) (i))

MOT #1 2019-03-08 15:58**MOT test number** 540102077082**Result** ✓ Passed

Advice Rear Tyres perishing

Advice Nearside Mirror damaged



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
11 April 2025

Tax status	Valid until 1 January
Days left	248
MOT expiry date	11 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-03-12
Last registration	2024-04-11
Complete history	See info



Registration #1	2016-03-12	13 mi
Registration #2	2019-03-08	57.660 mi
Registration #3	2020-03-11	76.250 mi
Registration #4	2020-03-11	76.250 mi
Registration #5	2020-03-11	76.250 mi
Registration #6	2021-04-12	79.735 mi
Registration #7	2021-03-29	79.735 mi
Registration #8	2021-03-29	79.735 mi
Registration #9	2021-03-29	79.735 mi
Registration #10	2021-03-29	79.735 mi
Registration #11	2021-03-29	79.735 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	86%
Children	85%
Pedestrian	74%
Safety systems	64%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1796 mm
Height	1600 mm
Length	4248 mm
Wheel base	2570 mm
Kerb weight	1320 kg
Max. allowed weight	1875 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2052615