



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D DRIVE R-DESIGN
Colour	Green
Year of manufacture	-
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2022-06-25
Pictures	11
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #17	2023-10-31 09:35
MOT test number	168311158141
Result	✓ Passed
Next expiry date	2024-10-30
Advice	Nearside Rear Nail in tyre
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush Slight Play (5.3.4 (a) (i))
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play Slight Play (5.3.4 (a) (i))

MOT #16	2023-10-31 09:35
MOT test number	471477509635
Result	✗ Failed
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush Slight Play (5.3.4 (a) (i))
Advice	Nearside Rear Nail in tyre
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Pass with rectification	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play Slight Play (5.3.4 (a) (i))

**MOT #15**

2022-08-20 09:24

MOT test number

811781784487

Result

✓ Passed

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Nail in tyre**MOT #14**

2021-09-16 12:44

MOT test number

347651478672

Result

✓ Passed

Advice Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Suspension arm pin or bush worn but not resulting in excessive movement Front wishbones rear bushes both sides deteriorated (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**MOT #13**

2021-09-16 12:44

MOT test number

995845916703

Result

✗ Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Suspension arm pin or bush worn but not resulting in excessive movement Front wishbones rear bushes both sides deteriorated (5.3.4 (a) (i))

**MOT #12** 2020-06-04 08:51**MOT test number** 351629173371**Result** ✓ Passed**MOT #11** 2019-05-16 09:23**MOT test number** 852148223971**Result** ✓ Passed**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear Child Seat fitted not allowing full inspection of adult belt both sides**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2019-05-16 09:23**MOT test number** 988002405965**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Child Seat fitted not allowing full inspection of adult belt both sides**Pass with rectification** Offside Headlamp light intensity severely reduced (4.1.4 (a))**MOT #9** 2018-05-23 13:52**MOT test number** 517964736846**Result** ✓ Passed

**MOT #8** 2018-05-23 12:46**MOT test number** 104188712655**Result** ✗ Failed**DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #7** 2017-05-25 08:28**MOT test number** 725872096598**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2016-06-01 15:54**MOT test number** 705521477938**Result** ✓ Passed**MOT #5** 2015-05-28 08:48**MOT test number** 887868045145**Result** ✓ Passed**MOT #4** 2015-05-28 08:48**MOT test number** 775678945161**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #3** 2014-05-01 10:08**MOT test number** 778061824168**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components



MOT #2	2014-04-29 14:11
MOT test number	289039814477
Result	✗ Failed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Under-trays fitted obscuring some underside components
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #1	2013-05-15 09:43
MOT test number	946255033133
Result	✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-05-28
Last registration	2023-10-31
Complete history	See info



Registration #1	2010-05-28	20 mi
Registration #2	2013-05-15	27.611 mi
Registration #3	2014-04-29	33.961 mi
Registration #4	2014-05-01	33.989 mi
Registration #5	2015-05-28	46.317 mi
Registration #6	2016-06-01	57.350 mi
Registration #7	2017-05-25	67.412 mi
Registration #8	2018-05-23	76.452 mi
Registration #9	2018-05-23	76.454 mi
Registration #10	2019-05-23	85.494 mi
Registration #11	2019-05-23	85.497 mi
Registration #12	2019-05-23	85.500 mi
Registration #13	2019-05-23	85.503 mi
Registration #14	2019-05-23	85.506 mi
Registration #15	2019-05-23	85.509 mi
Registration #16	2019-05-23	85.512 mi
Registration #17	2019-05-23	85.515 mi
Registration #18	2019-05-23	85.518 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1442 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	957553