



report date: 2024-03-28

General information

Make	FORD
Model	C-MAX TITANIUM 115
Colour	Silver
Year of manufacture	2009
Top speed	116 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	280 Nm at 1.900 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	62.8 mpg
Consumption combined	52.3 mpg
CO2 emission	143 g/km
CO2 label	F





Internet history

Entry 2

Date	2021-06-15
Pictures	0
Listing price	View report

source: autotrader.co.uk

Entry 1

Date	2021-06-14
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-21
MOT pass rate	60 %
MOT passed	12
Failed MOT tests	8
Total advice items	22
Total items failed	16

MOT #20	2023-07-12 11:10
MOT test number	532861333480
Result	✓ Passed
Next expiry date	2024-07-21

MOT #19	2023-07-12 11:10
MOT test number	537273420104
Result	✗ Failed
Pass with rectification Nearside Headlamp aim projected beam image is obviously incorrect bulb insecure (4.1.2 (c))	

MOT #18	2022-07-19 08:27
MOT test number	917135249964
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))	
Advice Play in steering rack inner joint(s)	

**MOT #17**

2022-07-18 07:35

MOT test number

918771201619

Result**✗ Failed****Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Play in steering rack inner joint(s)**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #16**

2021-06-29 06:16

MOT test number

402182897722

Result**✓ Passed****MOT #15**

2020-07-22 11:45

MOT test number

929670378979

Result**✓ Passed****Advice** Offside Rear Outer Tyre slightly damaged/cracking or perishing side wall damaged (5.2.3 (d) (ii))**Advice** Nearside Rear Outer Tyre slightly damaged/cracking or perishing side wall damaged (5.2.3 (d) (ii))**MOT #14**

2020-07-17 14:58

MOT test number

698600036040

Result**✗ Failed****Advice** Offside Rear Outer Tyre slightly damaged/cracking or perishing side wall damaged (5.2.3 (d) (ii))**Fail** Nearside Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Nearside Rear Outer Tyre slightly damaged/cracking or perishing side wall damaged (5.2.3 (d) (ii))

**MOT #13** 2019-07-03 10:14**MOT test number** 783583572987**Result** ✓ Passed**MOT #12** 2019-07-02 15:50**MOT test number** 420005512249**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Driver's view Items removed from driver's view prior to test things on mirror and screen (3.1 (a) (ii))**Fail** Rear Registration plate does not conform to the specified requirements white should be yellow (0.1 (d))**Fail** Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b))**MOT #11** 2018-06-15 10:28**MOT test number** 971757298669**Result** ✓ Passed**MOT #10** 2018-06-13 13:09**MOT test number** 132131999529**Result** ✗ Failed**Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (i))**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #9** 2017-12-08 11:07**MOT test number** 321429485183**Result** ✓ Passed**Advice** Front suspension has slight movement at a wishbone pin or bush both sides (2.5.A.1c)

**MOT #8** 2016-11-29 16:57**MOT test number** 383821692255**Result** ✓ Passed

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

Advice Undertrays and engine covers fitted unable to check certain items

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

MOT #7 2016-11-29 10:12**MOT test number** 431151526620**Result** ✗ Failed

Fail Front Windscreen washer provides insufficient washer liquid (8.2.3)

Advice Undertrays and engine covers fitted unable to check certain items

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

MOT #6 2015-12-16 15:48**MOT test number** 347812684665**Result** ✓ Passed**MOT #5** 2014-11-12 15:01**MOT test number** 266546514333**Result** ✓ Passed

**MOT #4** 2014-11-12 11:45**MOT test number** 776846314309**Result** ✗ Failed**Fail** Nearside Front coil spring broken (2.4.C.1a)**MOT #3** 2013-11-22 12:07**MOT test number** 946406223354**Result** ✓ Passed**MOT #2** 2012-05-10 16:56**MOT test number** 175011132160**Result** ✓ Passed**Advice** Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2012-05-10 12:09**MOT test number** 278031032457**Result** ✗ Failed**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
21 July 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	21 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	CK09UKV
Plate since	2024-03-28
Current registration	CK09UKV
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2009-05-14
Last registration	2023-07-12
Complete history	See info



Registration #1	2009-05-14	12 mi
Registration #2	2012-05-10	16.957 mi
Registration #3	2012-05-10	16.959 mi
Registration #4	2013-11-22	23.116 mi
Registration #5	2014-11-12	26.027 mi
Registration #6	2014-11-12	26.027 mi
Registration #7	2015-12-16	27.582 mi
Registration #8	2016-11-29	37.822 mi
Registration #9	2016-11-29	37.822 mi
Registration #10	2017-12-08	46.653 mi
Registration #11	2018-06-13	47.002 mi
Registration #12	2018-06-15	47.004 mi
Registration #13	2019-05-20	55.277 mi
Registration #14	2019-05-20	55.277 mi
Registration #15	2019-05-20	55.277 mi
Registration #16	2019-05-20	55.277 mi
Registration #17	2019-05-20	55.277 mi
Registration #18	2019-05-20	55.277 mi
Registration #19	2019-05-20	55.277 mi
Registration #20	2019-05-20	55.277 mi
Registration #21	2019-05-20	55.277 mi
Registration #22	2019-05-20	55.277 mi
Registration #23	2019-05-20	55.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1512 kg
Max. allowed weight	1995 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9J36113