



SM09CEU

report date: 2024-03-28

General information

Make	AUDI
Model	TT TFSI
Colour	White
Year of manufacture	2009
Top speed	149 mph
0 - 60 mph	6.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	200 BHP
Max. torque	279 Nm at 1.800 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	183 g/km
CO2 label	I








Internet history

Entry 2


Date	2021-06-29
Pictures	15
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-06-13
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-07
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	16
Total items failed	17

MOT #17	2023-12-21 09:20
MOT test number	414258815534
Result	✓ Passed
Next expiry date	2025-01-07
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #16	2022-12-15 14:54
MOT test number	667437465598
Result	✓ Passed
Advice	Induction pipe is missing
Advice	All rear suspension components are heavily corroded
Advice	Oil filler cap is damaged
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #15	2021-12-29 08:15
MOT test number	778977290169
Result	✓ Passed
Advice	Heavy underside corrosion to rear suspension components.

**MOT #14**

2021-12-21 15:34

MOT test number

670882512177

Result**✗ Failed****Advice** Heavy underside corrosion to rear suspension components.**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Fail** Windscreen washer not working (3.5 (a))**Fail** Rear Brake hose ferrule excessively corroded both sides (1.1.12 (f) (i))**Fail** Rear Brakes imbalanced across an axle (1.2.1 (b) (i))**Advice** Brake disc worn, pitted or scored, but not seriously weakened all brake discs corroded. (1.1.14 (a) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Exhaust has a minor leak of exhaust gases exhaust system poorly repaired, emissions test requirements only just met. (6.1.2 (a))**MOT #13**

2021-01-08 14:53

MOT test number

803955451246

Result**✓ Passed****MOT #12**

2021-01-04 14:58

MOT test number

291592459798

Result**✗ Failed****Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Front Driver's door cannot be opened from outside the vehicle (6.2.3 (a))**MOT #11**

2019-12-04 16:04

MOT test number

901219554493

Result**✓ Passed****Advice** Offside Front Tyre worn close to legal limit/worn on edge 225/50/17 (5.2.3 (e))

**MOT #10**

2019-12-03 16:51

MOT test number

618133404066

Result

✗ Failed

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 225/50/17 (5.2.3 (e))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #9**

2019-11-30 11:32

MOT test number

550770127910

Result

✗ Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Front Road wheel fixing missing (5.2.1 (a) (i))**Fail** Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Front Road wheel fixing missing (5.2.1 (a) (i))**Fail** Offside Rear Road wheel fixing missing (5.2.1 (a) (i))**MOT #8**

2018-10-12 12:11

MOT test number

363157461387

Result

✓ Passed



MOT #7	2017-05-05 13:50
MOT test number	634783079694
Result	✓ Passed
MOT #6	2016-05-09 11:59
MOT test number	126514066672
Result	✓ Passed
MOT #5	2015-05-06 15:18
MOT test number	737906225177
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
MOT #4	2015-05-06 15:18
MOT test number	186226325157
Result	✗ Failed
Pass with rectification	Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
MOT #3	2014-05-03 10:39
MOT test number	867043324117
Result	✓ Passed
MOT #2	2013-05-25 11:08
MOT test number	326895843125
Result	✓ Passed
MOT #1	2012-05-08 11:10
MOT test number	307319622166
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
7 January 2025

Tax status	Valid until 1 May
Days left	367
MOT expiry date	7 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-05-27
Last registration	2023-12-21
Complete history	See info



Registration #1	2009-05-27	20 mi
Registration #2	2012-05-08	38.262 mi
Registration #3	2013-05-25	43.170 mi
Registration #4	2014-05-03	46.807 mi
Registration #5	2015-05-06	50.011 mi
Registration #6	2016-05-09	53.238 mi
Registration #7	2017-05-05	60.343 mi
Registration #8	2018-10-12	67.132 mi
Registration #9	2019-11-30	76.079 mi
Registration #10	2019-12-03	76.144 mi
Registration #11	2020-05-20	76.277 mi
Registration #12	2021-05-20	76.277 mi
Registration #13	2022-05-20	76.277 mi
Registration #14	2023-05-20	76.277 mi
Registration #15	2023-05-20	76.277 mi
Registration #16	2023-05-20	76.277 mi
Registration #17	2023-05-20	76.277 mi
Registration #18	2023-05-20	76.277 mi
Registration #19	2023-05-20	76.277 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1842 mm
Height	1352 mm
Length	4178 mm
Wheel base	2468 mm
Kerb weight	1260 kg
Max. allowed weight	1660 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	BWA 266871