



report date: 2024-03-29

General information

Make	VOLVO
Model	V60 D2 BUSINESS EDITION
Colour	Red
Year of manufacture	2016
Top speed	121 mph
0 - 60 mph	10.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	280 Nm at 1.500 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	78.5 mpg
Consumption combined	74.3 mpg
CO2 emission	98 g/km
CO2 label	A







Internet history

Entry 1

Date	2021-09-24
Pictures	19
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-20
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	15
Total items failed	2

MOT #6 2023-09-25 08:29

MOT test number 452493324752

Result ✓ Passed

Next expiry date 2024-10-20

- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5 2022-09-23 08:43

MOT test number 196308689338

Result ✓ Passed

- Advice** Front Tyre worn close to legal limit/worn on edge Both worn on inner edge (5.2.3 (e))
- Advice** Brake disc worn, but not excessively lipped (1.1.14 (a) (i))

MOT #4 2021-10-21 12:11

MOT test number 114353530218

Result ✓ Passed

**MOT #3** 2020-12-16 17:21**MOT test number** 526096706245**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing slightly perished (5.2.3 (d) (ii))**Advice** Front under tray fitted**MOT #2** 2020-12-16 16:15**MOT test number** 166631362930**Result** ✗ Failed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing slightly perished (5.2.3 (d) (ii))**Advice** Front under tray fitted**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn 3mm (5.2.3 (e))**Fail** Offside Front Tyre has ply or cords damaged (5.2.3 (d) (ii))**MOT #1** 2019-12-04 12:09**MOT test number** 981602850366**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
20 October 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	20 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	RF66BZX
Plate since	2019-03-29
Current registration	RF66BZX
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2016-12-16
Last registration	2023-09-25
Complete history	See info



Registration #1	2016-12-16	14 mi
Registration #2	2019-12-04	27.244 mi
Registration #3	2020-12-16	39.166 mi
Registration #4	2020-12-16	39.166 mi
Registration #5	2023-09-25	39.166 mi
Registration #6	2023-09-25	39.166 mi
Registration #7	2023-09-25	39.166 mi
Registration #8	2023-09-25	39.166 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	2097 mm
Height	1484 mm
Length	4635 mm
Wheel base	2776 mm
Kerb weight	1617 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1787985