





report date: 2024-03-29

### General information

Make	RENAULT
Model	KANGOO ML19 DCI
Colour	White
Year of manufacture	2015
Top speed	150 mph
0 - 100 km/h	13.3 seconds
0 - 60 mph	16.3 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	66 kW / 90 HP / 75 BHP
Max. torque	180 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	67.3 mpg
Consumption combined	61.4 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-29

## Internet history

Entry	1

Lifety 1	
Date	2021-09-22
Pictures	0
Listing price	View report

source: yesauto.com

CarCheck.co.uk page 2/11



report date: 2024-03-29

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-10-20
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	1
Total items failed	8

MOT #8	2023-10-17 11:58
MOT test number	699723592295
Result	✓ Passed
Next expiry date	2024-10-20

MOT #7	2022-10-21 11:24
MOT test number	890993700973
Result	✓ Passed

MOT #6	2021-10-20 14:22
MOT test number	919096018618
Result	✓ Passed

MOT #		2021-10-08 14:5/
MOT te	st number	452897858231
Result		<b>X</b> Failed
Fail	Nearside Rear Rear reflector missing (4.8.2 (a) (ii))	
Fail	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	

MOT #4	2020-03-20 11:54
MOT test number	739862686863
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

**MOT** #3 2020-03-19 16:35 503722052802 **MOT** test number Result × Failed Fail Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail Nearside Front Road wheel badly distorted (5.2.2 (c) (i)) Fail Offside Front Brake pad(s) missing (1.1.13 (c)) Advice Nearside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e)) Fail Brake performance not tested due to really spongy pedal (1.2.1 (g))

MOT #2

MOT test number

320507835029

Result

✓ Passed

MOT test number

Result

Pass with rectification

Windscreen washer provides insufficient washer liquid (3.5 (a))

CarCheck.co.uk page 4/11



report date: 2024-03-29

### Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	20 October 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

## Owner history

Owner History	
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
********	
********	
*************	
	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	UK NK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-09-25
Last registration	2023-10-17
Complete history	See info



Registration #1	2015-09-25	6 mi
Registration #2	2018-11-01	32.661 mi
Registration #3	2018-11-01	32.661 mi
Registration #4	2020-03-19	50.932 mi
Registration #5	2020-03-20	50.934 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		10.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	2138 mm
Height	1805 mm
Length	4282 mm
Wheel base	2 mm
Kerb weight	1205 kg
Max. allowed weight	1884 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	2 page 11/1

Number of axles 2

**Engine number** D579568