



LRI4UWX

report date: 2024-03-29

General information

Make	FORD
Model	GALAXY TITANIUM TDCI
Colour	Black
Year of manufacture	-
Top speed	120 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg






Internet history

Entry 1

Date	2021-01-30
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)

**MOT history**

<b>MOT #10</b>	2022-03-29 12:05
<b>MOT test number</b>	802723451910
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-03-28
<b>Advice</b> Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement plus o/side trailing arms (5.3.4 (a) (i))	
<b>Advice</b> Front Body not fully secure bumper and slam panel (6.2.2 (a) (i))	

<b>MOT #9</b>	2021-03-24 15:32
<b>MOT test number</b>	307587899521
<b>Result</b>	✓ Passed
<b>Minor</b> Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
<b>Advice</b> Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

<b>MOT #8</b>	2020-07-07 08:27
<b>MOT test number</b>	550258361603
<b>Result</b>	✓ Passed
<b>Advice</b> Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
<b>Advice</b> Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
<b>Advice</b> Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
<b>Advice</b> Offside Front Drive shaft joint worn, but not excessively (6.1.7 (c) (i))	

<b>MOT #7</b>	2019-07-11 13:30
<b>MOT test number</b>	779824469910
<b>Result</b>	✓ Passed

<b>MOT #6</b>	2018-04-19 12:44
<b>MOT test number</b>	951394708109
<b>Result</b>	✓ Passed

**MOT #5** 2017-10-30 16:38**MOT test number** 406795848296**Result** ✓ Passed**MOT #4** 2017-10-30 14:27**MOT test number** 998485265886**Result** ✗ Failed

**Fail** Nearside Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Fail** Offside Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**MOT #3** 2017-04-19 12:52**MOT test number** 683475433191**Result** ✓ Passed**MOT #2** 2016-10-26 12:30**MOT test number** 831765016632**Result** ✓ Passed

**Advice** Engine cover fitted & under cover fitted

**MOT #1** 2016-04-28 10:00**MOT test number** 116871340690**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >





Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-05-07
Last registration	2022-03-29
Complete history	<a href="#">See info</a>



Registration #1	2014-05-07	12 mi
Registration #2	2016-04-28	58.156 mi
Registration #3	2016-10-26	73.739 mi
Registration #4	2017-04-19	88.635 mi
Registration #5	2017-10-30	105.660 mi
Registration #6	2017-10-30	105.660 mi
Registration #7	2017-10-30	105.660 mi
Registration #8	2017-10-30	105.660 mi
Registration #9	2017-10-30	105.660 mi
Registration #10	2017-10-30	105.660 mi
Registration #11	2017-10-30	105.660 mi
Registration #12	2017-10-30	105.660 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1688 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

<b>Number of axles</b>	2
<b>Engine number</b>	ET47075