



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D DRIVE R-DESIGN
Colour	Black
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-05-22
Pictures	27
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-11
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	15
Total items failed	11

MOT #16	2023-12-14 11:42
MOT test number	420470216589
Result	✓ Passed
Next expiry date	2025-01-11

MOT #15	2023-12-13 09:57
MOT test number	580137065944
Result	✗ Failed
Fail	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
Fail	Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
Fail	Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Nearside Parking brake inoperative on one side (1.4.1 (a))

**MOT #14** 2023-01-12 07:11**MOT test number** 637892589102**Result** ✓ Passed**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Direction indicator slightly discoloured both rear (4.4.3 (a))**Advice** Nearside Front Inner Tyre slightly damaged sidewall (5.2.3 (d) (ii))**Advice** Service brake fluctuating, but not excessively both front (1.2.1 (e))**MOT #13** 2021-05-24 08:43**MOT test number** 120065744458**Result** ✓ Passed**MOT #12** 2020-06-05 10:58**MOT test number** 217480235707**Result** ✓ Passed**MOT #11** 2019-08-14 13:15**MOT test number** 167402035916**Result** ✓ Passed**MOT #10** 2019-08-13 13:08**MOT test number** 388541200193**Result** ✗ Failed**Fail** Nearside Front Suspension arm pin or bush excessively worn bush (5.3.4 (a) (i))**Fail** Nearside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii))**Fail** Nearside Front Tyre has ply or cords exposed outer wall (5.2.3 (d) (ii))



MOT #9	2018-08-21 11:32
MOT test number	893598972051
Result	✓ Passed
MOT #8	2017-08-30 09:40
MOT test number	763280487205
Result	✓ Passed
MOT #7	2016-09-02 06:58
MOT test number	271940706217
Result	✓ Passed
MOT #6	2015-09-02 13:19
MOT test number	714873173593
Result	✓ Passed
MOT #5	2014-09-03 08:54
MOT test number	538956844244
Result	✓ Passed
MOT #4	2013-09-04 16:13
MOT test number	956347843241
Result	✓ Passed
MOT #3	2013-09-04 16:13
MOT test number	635697743284
Result	✗ Failed
<div>Pass with rectification Offside Front position lamp(s) not working (1.1.A.3b)</div>	

**MOT #2** 2013-04-22 17:10**MOT test number** 905182513109**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #1** 2013-04-17 16:49**MOT test number** 875807203170**Result** ✗ Failed**Notice** Offside front tyre has slight sidewall damage**Notice** Nearside front and offside front tyres tread wearing low on inside edge**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Nail in nearside rear tyre**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Notice** Offside rear tyre has small splits in its tread**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Notice** Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
11 January 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	11 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-04-17
Last registration	2023-12-14
Complete history	See info



Registration #1	2010-04-17	29 mi
Registration #2	2013-04-17	36.616 mi
Registration #3	2013-04-22	36.848 mi
Registration #4	2013-09-04	37.721 mi
Registration #5	2014-09-03	46.758 mi
Registration #6	2015-09-02	56.853 mi
Registration #7	2016-09-02	65.696 mi
Registration #8	2017-08-30	71.099 mi
Registration #9	2018-08-21	76.612 mi
Registration #10	2019-08-21	81.217 mi
Registration #11	2020-08-21	85.822 mi
Registration #12	2021-08-21	90.427 mi
Registration #13	2022-08-21	95.032 mi
Registration #14	2023-08-21	99.637 mi
Registration #15	2024-03-28	104.242 mi
Registration #16	2024-03-28	104.242 mi
Registration #17	2024-03-28	104.242 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1442 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	957553