



report date: 2024-03-28

General information

Make	VOLVO
Model	S40 D DRIVE S
Colour	Blue
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	108 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	104 g/km
CO2 label	B






Internet history

Entry 1

Date	2021-08-07
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-08
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	8
Total items failed	6

MOT #15	2023-11-14 10:21
MOT test number	841495319271
Result	✓ Passed
Next expiry date	2024-12-08

MOT #14	2022-11-30 10:08
MOT test number	781302210587
Result	✓ Passed
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #13	2021-11-15 09:18
MOT test number	559899163919
Result	✓ Passed
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #12	2020-12-02 13:25
MOT test number	331789467929
Result	✓ Passed

MOT #11	2019-11-12 16:36
MOT test number	623879747575
Result	✓ Passed



MOT #10	2018-12-07 11:27
MOT test number	965374062857
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #9	2017-12-01 11:30
MOT test number	949162979587
Result	✓ Passed

MOT #8	2017-11-30 10:00
MOT test number	434748556482
Result	✗ Failed
Fail	Nearside Front position lamp(s) not working (1.1.A.3b)
Fail	Offside Registration plate lamp not working (1.1.C.1d)
Fail	Nearside Registration plate lamp not working (1.1.C.1d)
Fail	Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)

MOT #7	2016-12-09 09:28
MOT test number	219292917501
Result	✓ Passed

MOT #6	2016-07-21 07:44
MOT test number	464620162944
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2015-08-13 09:42**MOT test number** 208815825294**Result** ✓ Passed**MOT #4** 2014-08-15 08:47**MOT test number** 799907524217**Result** ✓ Passed**MOT #3** 2013-08-28 11:07**MOT test number** 915390643213**Result** ✓ Passed**Notice** Plastic covers fitted under engine and outer sills**MOT #2** 2013-08-22 12:11**MOT test number** 765084133261**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Plastic covers fitted under engine and outer sills**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #1** 2012-09-21 15:25**MOT test number** 388905862450**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
8 December 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	8 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX XXXX
Date of agreement	XXXXXXXXXX XXXX
Agreement type	XXXXXXXXXX XXXX
Agreement term	XXXXXXXXXX XXXX
Agreement number	XXXXXXXXXX XXXX
Contact info	XXXXXXXXXX XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-10-30
Last registration	2023-11-14
Complete history	See info



Registration #1	2009-10-30	17 mi
Registration #2	2012-09-21	50.153 mi
Registration #3	2013-08-22	58.917 mi
Registration #4	2013-08-28	58.921 mi
Registration #5	2014-08-15	61.338 mi
Registration #6	2015-08-13	68.324 mi
Registration #7	2016-07-21	72.450 mi
Registration #8	2016-12-09	73.893 mi
Registration #9	2017-11-30	81.409 mi
Registration #10	2018-05-22	85.377 mi
Registration #11	2018-05-22	85.377 mi
Registration #12	2018-05-22	85.377 mi
Registration #13	2018-05-22	85.377 mi
Registration #14	2018-05-22	85.377 mi
Registration #15	2018-05-22	85.377 mi
Registration #16	2018-05-22	85.377 mi
Registration #17	2018-05-22	85.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1408 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	884000
---------------	--------