





report date: 2024-03-28

General information

Make	FIAT
Model	500X MULTIJET CROSS
Colour	Red
Year of manufacture	2015
Top speed	115 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	74.3 mpg
Consumption combined	68.9 mpg
CO2 emission	109 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history


Entry 1

Date 2021-05-26

Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history	
-------------	--

MOT expiry date	2024-05-07
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	11
Total items failed	1

MOT #7	2023-05-02 16:40
MOT test number	209704278281
Result	✓ Passed
Next expiry date	2024-05-07

MOT #6	2022-04-28 15:54
MOT test number	818653994869
Result	✓ Passed

MOT #5	2021-05-08 10:01
MOT test number	410523423967
Result	√ Passed

MOT #4	2020-10-30 13:04
MOT test number	949032219843
Result	✓ Passed

MOT #3	2020-10-30 11:53
MOT test number	612885661133
Result	× Failed
Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #2		2019-10-28 11:46
MOT test	number	201973521736
Result		✓ Passed
Advice	Tyre pressure monitoring system warning lamp on for low tyre pressure	
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn low on outer	edges (5.2.3 (e))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn low on oute	er edges (5.2.3 (e))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #1	2018-10-24 08:40
MOT test number	483207808033
Result	✓ Passed
Advice Offside Rear Nail in tyre	
Minor Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))	
Advice Items removed from driver's view prior to test	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	7 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report $\underline{\mathbf{k}}$	
HARMAN CO. C.	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	NIE UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-10-31
Last registration	2023-05-02
Complete history	See info



Registration #1	2015-10-31	17 mi
Registration #2	2018-10-24	19.351 mi
Registration #3	2019-10-28	25.181 mi
Registration #4	2020-10-30	30.615 mi
Registration #5	2020-10-30	30.616 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
60482	
60501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	86%
Children	85%
Pedestrian	74%
Safety systems	64%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1796 mm
Height	1608 mm
Length	4273 mm
Wheel base	2570 mm
Kerb weight	1320 kg
Max. allowed weight	1875 kg

Additional information

Fuel tank capacity	48 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 1	1/11

Number of axles2Engine number7511554