





report date: 2024-03-28

General information

Make	BMW
Model	Z3 Z3 ROADSTER
Colour	Green
Year of manufacture	1998
Top speed	128 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	180 Nm at 4.300 rpm
Engine capacity	1.895 сс
Cylinders	4
Fuel type	Petrol
Consumption city	24.8 mpg
Consumption extra urban	47.1 mpg
Consumption combined	35.3 mpg



CarCheck.co.uk page 1/17



report date: 2024-03-28

Internet history

Entry 1

Date 2022-05-20

Pictures 33

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/17



report date: 2024-03-28

MOT history

MOT expiry date	2024-05-30
MOT pass rate	65 %
MOT passed	17
Failed MOT tests	9
Total advice items	86
Total items failed	17

MOT #26		2023-05-19 11:06
MOT test	number	566921227550
Result		√ Passed
Next expi	ry date	2024-05-30
Advice	Brake pipes rusty	
Advice	Rear suspension rusty	
Advice	Osf brake hose cracking	
Advice	Exhaust rusty	

MOT #25	2022-05-31 15:43
MOT test number	832413902592
Result	✓ Passed

Result	✓ Passed
MOT #	24 2022-05-31 13:18
MOT te	est number 766919704704
Result	★ Failed
Advice (b))	Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4
Fail (b))	Nearside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4
Fail	Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))

CarCheck.co.uk page 3/17



report date: 2024-03-28

MOT #23	2021-12-01 09:49
MOT test number	866305194118
Result	✓ Passed
Advice Offside Front tyre is perished between tread	
Advice Nearside Front tyre is perished between tread	

MOT #22		2020-12-11 12:57
MOT test	number	101317158867
Result		✓ Passed
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Minor	Nearside Windscreen wiper blade defective (3.4 (b) (i))	
Minor	Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Offside Rear Valve stem slightly damaged Valve leaking air (5.2.3 (j))	
Minor	Nearside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))	
Advice	Offside Front Valve stem slightly damaged (5.2.3 (j))	

MOT #21	2019-05-01 12:44
MOT test number	355050299796
Result	✓ Passed
MOT #20	2018-05-16 12:36
MOT test number	223254530114
Result	✓ Passed

CarCheck.co.uk page 4/17



report date: 2024-03-28

MOT #19 2018-05-08 10:51

MOT test number 705460651950

Result X Failed

Fail Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)

Fail Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)

MOT #18 2017-04-27 14:03

MOT test number 584297226577

Result ✓ Passed

MOT #17 2017-04-10 11:45

MOT test number 587458938690

Result X Failed

Fail Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)

Fail Nearside Front All position lamps not working (1.1.A.3b)

MOT #16 2015-04-22 11:07

MOT test number 108302615150

Advice Nearside Brake pipe slightly corroded (3.6.B.2c)

Advice Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

Notice Play in steering rack inner joint(s)

Advice Nearside Headlamp deteriorated but light output not reduced (1.7.5a)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Notice Exhaust deteriorating

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

Advice Offside Headlamp deteriorated but light output not reduced (1.7.5a)

CarCheck.co.uk page 5/17



report date: 2024-03-28

MOT #15	2015-04-22 11:07
MOT test number	856582515179
Result	× Failed
Advice Front Brake pad(s) wearing thin (3.5.1g)	
Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice Offside Headlamp deteriorated but light output not reduced (1.7.5a)	
Notice Exhaust deteriorating	
Pass with rectification Offside Front position lamp(s) not working (1.1.A.3b)	
Advice Nearside Brake pipe slightly corroded (3.6.B.2c)	
Advice Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)	
Advice Nearside Headlamp deteriorated but light output not reduced (1.7.5a)	
Notice Play in steering rack inner joint(s)	

MOT #14		2014-05-02 15:35
MOT test	number	708252724104
Result		✓ Passed
Advice	Nearside Front Headlamp deteriorated but light output not reduced (1.7.5a)	
Notice	Rear exhaust box deteriorated	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Offside Front Headlamp deteriorated but light output not reduced (1.7.5a)	
Notice	Play in steering rack inner joint(s)	
Advice	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)	

CarCheck.co.uk page 6/17



report date: 2024-03-28

MOT #13		2013-04-25 13:21
MOT test	number	799235313110
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Headlamp deteriorated but light output not reduced (1.7.5a)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Headlamp deteriorated but light output not reduced (1.7.5a)	
Notice	Exhaust rear section rusty	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #12		2013-04-25 13:21
MOT test	number	227325213436
Result		× Failed
Advice	Offside Front Headlamp deteriorated but light output not reduced (1.7.5a)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Exhaust rear section rusty	
Advice	Nearside Front Headlamp deteriorated but light output not reduced (1.7.5a)	
Advice	Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Pass with rectification Nearside Front position lamp(s) not working (1.1.A.3b)		

CarCheck.co.uk page 7/17



report date: 2024-03-28

MOT test number

279394402190

Result

Notice Nearside front tyre perished and close to limit

Advice Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Notice Offside front tyre close to limit

Notice C.o on limit, on fast and natural idle

MOT #10		2010-10-04 15:47
MOT test	number	872587570292
Result		✓ Passed
Advice	Nearside Front Shock absorber has a light misting of oil (2.7.3)	
Notice	N/s inner washer jet blocked	
Advice	Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)	
Notice	Exhaust system corroded	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)	
Notice	Front outer headlamp lenses faded	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 8/17



report date: 2024-03-28

MOT #9 2010-09-27 10:48 104210870225 **MOT** test number Result × Failed **Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3) **Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2) Fail Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4) Notice Front outer headlamp lenses faded Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1) Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2) **Advice** Fail Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3) **Notice** N/s inner washer jet blocked Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) Notice Exhaust system corroded **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #8		2009-09-22 09:32
MOT test	number	173725569223
Result		✓ Passed
Notice	Slight weep from n/s/f shock absorber	
Notice	Fuel tank straps starting to corrode	

MOT #7	2008-09-30 14:38
MOT test number	984894078243
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 9/17



report date: 2024-03-28

MOT #6 2007-09-12 16:21

MOT test number 812565557268

MOT #5 2007-09-11 10:35

MOT test number 302674157232

Result X Failed

Advice Offside Headlamp not in a clean condition but not affecting beam image (1.2.4a)

Notice Slight play in steering rack detected at both front wheels

Fail Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)

Advice Nearside Headlamp not in a clean condition but not affecting beam image (1.2.4a)

Fail Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)

MOT #4 2006-09-04 14:19

MOT test number 841837846238

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #3 2006-08-30 17:56

MOT test number 141972046253

Result X Failed

Fail Offside Windscreen washer provides insufficient washer liquid (8.2.3)

Fail Nearside Rear coil spring corroded so that its cross sectional area is reduced and seriously weakened (2.4.C.1b)

Fail Offside Rear coil spring fractured (2.4.C.1a)


Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 10/17



report date: 2024-03-28





CarCheck.co.uk page 11/17



report date: 2024-03-28

Tax & MOT check



Days left 216

MOT expiry date 30 May 2024

Full MOT history See MOT history

CarCheck.co.uk page 12/17



report date: 2024-03-28

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 13/17



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this BMW? How many owners di Check it in the premium report and see all owner registrations. Download the full report <u>has</u>		ve?
THE STATE OF THE S		

	More info	>
Plate changes		
See in this check if this BMW had different number plates.		
Number of plates		
Current registration	NK NA	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 14/17



report date: 2024-03-28

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 15/17



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	1998-05-13
Last registration	2023-05-19
Complete history	See info



Registration #1	1998-05-13	11 mi
Registration #2	2005-12-20	64.485 mi
Registration #3	2005-12-20	64.485 mi
Registration #4	2006-08-30	67.771 mi
Registration #5	2006-09-04	67.835 mi
Registration #6	2007-09-11	74.314 mi
Registration #7	2007-09-12	74.321 mi
Registration #8	2008-09-30	79.591 mi
Registration #9	2009-09-22	85.609 mi
Registration #10	2010-09-27	90.094 mi
Registration #11	2010-10-04	90.096 mi
Registration #12	2012-04-13	90.623 mi
Registration #13	2013-04-25	95.546 mi
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		11.777 es
Registration #24		11.777 es
Registration #25		11.777 es
Registration #26		71,777 es

CarCheck.co.uk page 16/17



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
0482	
0501	
0566	
60567	
60569	

Safety ratings

NCAP rating	*****
Video	see crash video



Additional information

Fuel tank capacity	51
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	07228873

CarCheck.co.uk page 17/17