





General information

Make	MINI
Model	ONE
Colour	Black
Year of manufacture	2016
Top speed	121 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	101 BHP	0 <
Max. torque	180 Nm at 1.400 rpm	101 - 1
Engine capacity	1.198 cc	121 - 140
Cylinders	3	141 - 165
Fuel type	Petrol	166 - 185
Consumption city	49.6 mpg	186 - 225
Consumption extra urban	70.6 mpg	225+
Consumption combined	61.4 mpg	
CO2 emission	108 g/km	
CO2 label	В	






Internet history

Entry 1	
Date	2021-10-07
Pictures	14
Listing price	View report









source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-05
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	19
Total items failed	0

MOT #7	2023-06-03 15:29
MOT test number	204254111446
Result	✓ Passed
Next expiry date	2024-06-05
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Minor Offside Front Windscreen damaged but not adversely affecting driver's view (3.	2 (a) (i))
Advice Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))	
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	

MOT #6	2023-06-03 15:12
MOT test number	498406051670
Result	🗙 Failed
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
DANGEROUS Offside Rear Inner Tyre has a bulge, caused by separation or partial Sidewall (5.2.3 (d) (ii))	failure of its structure
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
DANGEROUS Nearside Front Outer Tyre has a bulge, caused by separation or par structure sidewall (5.2.3 (d) (ii))	tial failure of its
Minor Offside Front Windscreen damaged but not adversely affecting driver's view	v (3.2 (a) (i))
Advice Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))	





MOT #5		2022-05-31 09:23
MOT test	number	467184699835
Result		✓ Passed
Advice	Nearside Front Tyre slightly damaged outer side wall areas (5.2.3 (d) (ii))	
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Items removed from driver's view prior to test	
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))	

MOT #4	2021-05-11 12:33
MOT test number	358775909487
Result	Passed
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #3	2020-06-06 09:07
MOT test number	979206691502
Result	✓ Passed

MOT #2	2019-03-16 15:37
MOT test number	960320573797
Result	✓ Passed

MOT #1	2019-03-16 14:38
MOT test number	448408808015
Result	🗙 Failed
Minor Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))	
DANGEROUS Offside Rear Tyre has a bulge, caused by separation or partial failure of	of its structure 175-
65-15 (5.2.3 (d) (ii))	



Tax & MOT check

Taxed Tax due: 1 November 2024	✓ MOT Expires: 5 June 2024
Tax status	Valid until 1 November
Days left	187
MOT expiry date	5 June 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-





Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

Extra MINI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-03-04
Last registration	2023-06-03
Complete history	See info



Registration #1	2016-03-04	14 mi
Registration #2	2019-03-16	43.555 mi
Registration #3	2019-03-16	43.558 mi
Registration #4	2020-06-06	53.784 mi
Registration #5	2021-05-11	59.306 mi
Registration #6		11.117 est
Registration #7		11.177 esi
Registration #8		11.117 esi
Registration #9		11.777 esi

More info >





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1727 mm
Height	1414 mm
Length	3821 mm
Wheel base	2495 mm
Kerb weight	1090 kg
Max. allowed weight	1570 kg
Additional information	
Fuel tank capacity	40
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 11/11

Number of axles	2
Engine number	F119H161