




report date: 2024-03-28

General information

Make	VOLVO
Model	C30 SPORT
Colour	Blue
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	167 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-02-06
Pictures	9
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-12-20
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	12
Total items failed	16

MOT #19	2023-12-21 11:48
MOT test number	359289527677
Result	✓ Passed
Next expiry date	2024-12-20

MOT #18	2023-11-16 12:05
MOT test number	580605730422
Result	✗ Failed
MAJOR	Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17	2022-11-15 15:30
MOT test number	251690990919
Result	✓ Passed
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #16	2021-11-20 12:02
MOT test number	257989644648
Result	✓ Passed



MOT #15	2021-11-20 12:02
MOT test number	852706665816
Result	✗ Failed
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #14	2020-09-16 10:44
MOT test number	559757658591
Result	✓ Passed

MOT #13	2020-09-16 08:16
MOT test number	911432377096
Result	✗ Failed
DANGEROUS	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))
DANGEROUS	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Pass with rectification	Nearside Front Outline marker lamp not working (4.2.1 (a) (iii))

MOT #12	2018-12-19 09:49
MOT test number	972526857759
Result	✓ Passed

MOT #11	2018-12-17 16:41
MOT test number	963599672554
Result	✗ Failed
MAJOR	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))



MOT #10	2018-02-10 11:59
MOT test number	982231295252
Result	✓ Passed
Advice	Parking brake lever has little reserve travel (3.1.6b)

MOT #9	2018-02-09 16:38
MOT test number	403701812051
Result	✗ Failed
Pass with rectification	Offside Registration plate lamp not working (1.1.C.1d)
Fail	Offside Front Suspension arm has excessive play in a pin/bush Rear track control bush (2.4.G.2)
Fail	Offside Rear Valve stem seriously damaged (4.1.D.1e)
Fail	Nearside Front Valve stem seriously damaged (4.1.D.1e)
Advice	Parking brake lever has little reserve travel (3.1.6b)
Pass with rectification	Offside Headlamp not working on dipped beam (1.7.5a)
Fail	Nearside Front Suspension arm has excessive play in a pin/bush Rear track control bush (2.4.G.2)
Fail	Nearside Rear Valve stem seriously damaged (4.1.D.1e)
Pass with rectification	Windscreen wiper does not clear the windscreen effectively Both (8.2.2)

MOT #8	2017-02-10 14:21
MOT test number	653769809018
Result	✓ Passed



MOT #7 2017-02-10 14:21

MOT test number 464311316902

Result ✗ Failed

- Pass with rectification** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)
- Pass with rectification** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #6 2016-02-12 11:40

MOT test number 174448199515

Result ✓ Passed

- Advice** Nearside Rear tyre cracking due to age
- Advice** Offside Rear tyre cracking due to age

MOT #5 2015-02-06 13:11

MOT test number 405907835016

Result ✓ Passed

MOT #4 2014-02-18 10:14

MOT test number 256909244007

Result ✓ Passed

MOT #3 2014-02-17 16:55

MOT test number 237328644032

Result ✗ Failed

- Fail** Nearside Rear Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Offside Rear Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)



MOT #2	2013-03-07 16:23
---------------	------------------

MOT test number	477916763053
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2012-10-15 16:30
---------------	------------------

MOT test number	907259482219
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
20 December 2024

Tax status Valid until 1 June

Days left 33

MOT expiry date 20 December 2024

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	DV59KNP
Plate since	2024-03-28
Current registration	DV59KNP
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled. If not, and you buy this VOLVO then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-11-20
Last registration	2023-12-21
Complete history	See info



Registration #1	2009-11-20	26 mi
Registration #2	2012-10-15	20.275 mi
Registration #3	2013-03-07	21.330 mi
Registration #4	2014-02-17	23.303 mi
Registration #5	2014-02-18	23.303 mi
Registration #6	2015-02-06	31.437 mi
Registration #7	2016-02-12	40.733 mi
Registration #8	2017-02-10	47.440 mi
Registration #9	2017-02-10	47.440 mi
Registration #10	2018-02-09	54.453 mi
Registration #11	2018-02-10	54.453 mi
Registration #12	2019-02-09	61.466 mi
Registration #13	2019-02-10	61.466 mi
Registration #14	2019-02-10	61.466 mi
Registration #15	2019-02-10	61.466 mi
Registration #16	2019-02-10	61.466 mi
Registration #17	2019-02-10	61.466 mi
Registration #18	2019-02-10	61.466 mi
Registration #19	2019-02-10	61.466 mi
Registration #20	2019-02-10	61.466 mi
Registration #21	2023-12-21	61.466 mi

[More info >](#)



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1277 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Engine number

156670