





report date: 2024-03-29

### General information

Make	PEUGEOT
Model	BOXER HDI 335 L3H2 PROFESSIONAL P/V
Colour	White
Year of manufacture	2016
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	130 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	44.8 mpg
Consumption combined	38.2 mpg
CO2 emission	195 g/km
CO2 label	1



CarCheck.co.uk page 1/12



report date: 2024-03-29

### Internet history

### Entry 1

Date	2021-12-18
Pictures	1
Listing price	View report



source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2025-03-05
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	20
Total items failed	1

MOT #8	2024-03-04 08:05
MOT test number	891420018090
Result	<b>✓</b> Passed
Next expiry date	2025-03-05

MOT #7	2023-02-21 13:50
MOT test number	906734504842
Result	✓ Passed
Advice Supplementary restraint system warning lamp does not illuminate (7.1.6 (a))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #6 2023-02-15 14:20

**MOT test number** 103050454462

**Result** X Failed

**MAJOR** Engine mounting damaged or deteriorated resulting in excessive movement engine stabilizer (6.1.8 (a) (i))

MAJOR Offside Front Brake hose excessively twisted (1.1.12 (b) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

MAJOR Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MAJOR** Offside Obligatory mirror seriously damaged, affecting the rear view sharp edges + glass insecure (3.3 (b) (ii))

MOT #5 2022-03-02 14:59

**MOT test number** 832011767436

**Result** 
✓ Passed

**Advice** Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #4 2021-03-04 13:48

MOT test number 158448073161

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #3

MOT test number

Result

Advice

Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #2

MOT test number

609762681849

Result

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Pass with rectification (4.1.2 (c))

MOT test number

954036469006

Result

Minor Nearside Obligatory mirror slightly damaged (3.3 (b) (i))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Offside Obligatory mirror slightly damaged (3.3 (b) (i))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 5/12



report date: 2024-03-29

### Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	5 March 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12




report date: 2024-03-29

### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

# Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many own have? Check it in the premium report and see all owner registrations. Download the full	
********	
***************************************	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	OR STATES
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

### Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-02-22
Last registration	2024-03-04
Complete history	See info



Registration #1	2016-02-22	8 mi
Registration #2	2019-02-11	62.370 mi
Registration #3	2020-03-06	84.420 mi
Registration #4	2020-03-06	84.420 mi
Registration #5	2021-03-04	124.277 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		77.777 au

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

### Safety ratings

NCAP rating	****
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	see crash video



### Additional information

Fuel tank capacity	90 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	TRJA0925482

CarCheck.co.uk page 12/12