



report date: 2024-03-28

## General information

Make	VOLKSWAGEN
Model	PASSAT HIGHLINE TSI
Colour	Blue
Year of manufacture	2009
Top speed	134 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	160 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.790 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	44.8 mpg
Consumption combined	34.5 mpg
CO2 emission	195 g/km
CO2 label	J






Internet history

Entry 2

Date	2022-07-21
Pictures	50
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

Entry 1

Date	2021-09-19
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-06-04
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	42
Total items failed	6

MOT #15 2023-06-05 12:02

MOT test number 883947071137

Result ✓ Passed

Next expiry date 2024-06-04

**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

**Advice** Front Brake disc worn, but not excessively both side front (1.1.14 (a) (i))

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #14 2022-07-20 14:58

MOT test number 833007880478

Result ✓ Passed

MOT #13 2021-05-27 08:10

MOT test number 725102056156

Result ✓ Passed

MOT #12 2020-06-05 13:29

MOT test number 952525644082

Result ✓ Passed

**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11**

2019-05-30 13:36

**MOT test number**

546757834858

**Result**

✓ Passed

**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))**MOT #10**

2019-05-30 09:47

**MOT test number**

424970098881

**Result**

✗ Failed

**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm Inner edge (5.2.3 (e))**Fail** Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt Both sides (5.3.4 (b) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #9**

2018-06-18 12:26

**MOT test number**

942028462236

**Result**

✓ Passed

- Advice** Radiator weeping
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Windscreen chipped
- Advice** Under shield
- Advice** O/s/f tyre showing deterioration
- Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Engine cover
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge deteriorated and cracked (5.2.3 (e))

**MOT #8**

2017-06-20 14:58

**MOT test number**

465616232519

**Result**

✓ Passed

- Advice** Under shield
- Advice** Nearside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Engine cover
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** O/s/r tyre deteriorated and cracked in tread and sidewall



MOT #7 2017-06-19 12:28

MOT test number 797693246522

Result ✗ Failed

- Advice** Engine cover
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** O/s/r tyre deteriorated and cracked in tread and sidewall
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Advice** Under shield
- Advice** Nearside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

MOT #6 2016-02-25 15:28

MOT test number 410578572007

Result ✓ Passed

- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Engine cover
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** O/s/r tyre showing deterioration
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Undershield

**MOT #5** 2016-02-24 13:15**MOT test number** 569093440145**Result** ✗ Failed

- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Undershield
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Engine cover
- Fail** Offside Rear coil spring broken (2.4.C.1a)
- Advice** O/s/r tyre showing deterioration
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #4** 2015-02-06 15:04**MOT test number** 738087235034**Result** ✓ Passed**MOT #3** 2014-02-18 14:25**MOT test number** 567549344061**Result** ✓ Passed**MOT #2** 2012-12-28 09:19**MOT test number** 377563362378**Result** ✓ Passed

- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #1** 2011-12-28 10:58**MOT test number** 527662361327**Result** ✓ Passed

- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 May 2025

✓  
**MOT**  
  
Expires:  
4 June 2024

Tax status	Valid until 1 May
Days left	367
MOT expiry date	4 June 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-01-09
Last registration	2023-06-05
Complete history	<a href="#">See info</a>



Registration #1	2009-01-09	10 mi
Registration #2	2011-12-28	93.350 mi
Registration #3	2012-12-28	128.273 mi
Registration #4	2014-02-18	128.685 mi
Registration #5	2015-02-06	136.095 mi
Registration #6	2016-02-24	139.831 mi
Registration #7	2016-02-25	139.831 mi
Registration #8	2017-06-19	145.376 mi
Registration #9	2017-06-20	145.376 mi
Registration #10	2018-06-20	151.921 mi
Registration #11	2019-06-20	158.466 mi
Registration #12	2020-06-20	165.011 mi
Registration #13	2021-06-20	171.556 mi
Registration #14	2022-06-20	178.101 mi
Registration #15	2023-06-05	184.646 mi
Registration #16		
Registration #17		
Registration #18		

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Max. allowed weight	2070 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

**Number of axles**

2

**Engine number**

BZB 089653