



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE SPORT TDI DSG
Colour	Red
Year of manufacture	2014
Top speed	121 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	103 kW / 140 HP / 138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	61.4 mpg
Consumption combined	52.3 mpg
CO2 emission	140 g/km
CO2 label	E





Internet history

Entry 1

Date	2022-06-30
Pictures	5
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-10
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	20
Total items failed	8

MOT #11	2023-10-11 10:51
MOT test number	884982211416
Result	✓ Passed
Next expiry date	2024-10-10
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #10	2022-10-04 10:54
MOT test number	496401028341
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin all fronts worn low (1.1.13 (a) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both fronts (1.1.14 (a) (ii))

**MOT #9**

2022-09-28 13:03

MOT test number

990117694114

Result**✗ Failed**

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both fronts (1.1.14 (a) (ii))

Advice Front Brake pad(s) wearing thin all fronts worn low (1.1.13 (a) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing cracking on side wall (5.2.3 (d) (ii))

Fail Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both rears (1.1.14 (a) (ii))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge outer and inner edges worn (5.2.3 (e))

Fail Rear fog lamp not working (4.5.1 (a) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing perished (5.2.3 (d) (ii))

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear nail in tread pattern

MOT #8

2022-01-21 12:52

MOT test number

789636695227

Result**✓ Passed**

Advice Nearside Front Tyre worn close to legal limit/worn on edge edge badly worn (5.2.3 (e))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))

**MOT #7** 2022-01-21 11:56**MOT test number** 292150554647**Result** ✗ Failed**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge edge badly worn (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))**MOT #6** 2021-01-20 11:10**MOT test number** 472808615148**Result** ✓ Passed**MOT #5** 2019-10-04 13:16**MOT test number** 122804861758**Result** ✓ Passed**MOT #4** 2018-12-12 12:40**MOT test number** 303625591088**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**Advice** Rear Passenger seat(s) missing at time of test**MOT #3** 2018-01-03 09:36**MOT test number** 856970540031**Result** ✓ Passed**MOT #2** 2016-12-07 16:04**MOT test number** 801392973464**Result** ✓ Passed**Advice** Front tyres 3ml centre but worn right down on edge



MOT #1	2016-12-07 11:04
MOT test number	508433716144
Result	✗ Failed
Fail	Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)
Advice	Front tyres 3ml centre but worn right down on edge



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
10 October 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	10 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-01-06
Last registration	2023-10-11
Complete history	See info



Registration #1	2014-01-06	27 mi
Registration #2	2016-12-07	33.201 mi
Registration #3	2016-12-07	33.203 mi
Registration #4	2018-01-03	46.348 mi
Registration #5	2018-12-12	53.526 mi
Registration #6	2019-10-04	59.240 mi
Registration #7	2021-01-20	60.816 mi
Registration #8	2023-10-11	61.277 mi
Registration #9	2023-10-11	61.277 mi
Registration #10	2023-10-11	61.277 mi
Registration #11	2023-10-11	61.277 mi
Registration #12	2023-10-11	61.277 mi
Registration #13	2023-10-11	61.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	90%
Pedestrian	53%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2021 mm
Height	1486 mm
Length	4278 mm
Wheel base	2537 mm
Kerb weight	1359 kg
Max. allowed weight	1870 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	CFFBH54051