





report date: 2024-03-28

General information

Make	MERCEDES
Model	S-Class S320 CDI
Colour	Grey
Year of manufacture	2008
Top speed	149 mph
0 - 60 mph	7.5 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	231 BHP
Max. torque	540 Nm at 1.600 rpm
Engine capacity	2.987 сс
Cylinders	6
Fuel type	Diesel
Consumption city	24.4 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.0 mpg
CO2 emission	225 g/km
CO2 label	K



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

		1
ᆮ	HLIV	-

Date	2021-09-08
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

MOT expiry date	2024-09-24
MOT pass rate	93 %
MOT passed	13
Failed MOT tests	1
Total advice items	23
Total items failed	2

MOT #14		2023-09-06 11:42
MOT test	number	301179141553
Result		✓ Passed
Next expi	ry date	2024-09-24
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #13		2022-09-14 12:07
MOT test	number	852089601100
Result		✓ Passed
Advice	Tyre worn close to legal limit/worn on edge All 4 tyres (5.2.3 (e))	
Advice	Offside Front Wheel bearing has slight play (5.1.3 (a) (i))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #12 2021-09-25 13:19

MOT test number 147558151072

Result ✓ Passed

Advice Offside Front Brake pipe corroded, covered in grease or other material coated in sealer (1.1.11 (c))

Advice Offside Rear Tyre worn close to legal limit/worn on edge 255/45/18 inside edge worn close to cords/ply (5.2.3 (e))

Advice Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 255/45/18 inside edge worn close to cords/ply (5.2.3 (e))

Advice Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11 2020-11-03 12:10

MOT test number 644608030205

Result ✓ Passed

MOT #10 2019-10-08 13:49

MOT test number 560433114700

Advice Offside Rear Outer Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

Advice Nearside Rear Outer Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

MOT #9 2018-11-09 11:20

MOT test number 629676465205

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

CarCheck.co.uk page 4/13



FP58KPR

report date: 2024-03-28

MOT #8	2017-11-06 14:50
MOT test number	317394228131
Result	✓ Passed
Advice Rear Brake pipe slightly corroded (3.6.B.2c)	

MOT #7	2016-11-11 10:41
MOT test number	896231075867
Result	✓ Passed
Advice Front wheel bearing has slight play (2.5.A.3c)	

MOT #6	2015-11-04 10:40
MOT test number	877315443372
Result	✓ Passed

MOT #5	2014-11-11 09:49
MOT test number	189805314384
Result	✓ Passed

MOT #4	2013-11-14 10:56
MOT test number	185988313325
Result	.✓ Passed

MOT #3		2012-11-15 10:52
MOT test	number	199020722352
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT test number

537060222386

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

 MOT #1
 2011-12-08 12:29

 MOT test number
 566302241326

 Result
 ✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	24 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-28


Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	



Extra MERCEDES salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



FP58KPR report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many own MERCEDES have? Check it in the premium report and see all owner registrations. Downloaner.	

Plate changes	More info >
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	ak (
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



FP58KPR report date: 2024-03-28

Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2008-12-31
Last registration	2023-09-06
Complete history	See info



Registration #1	2008-12-31	10 mi
Registration #2	2011-12-08	19.421 mi
Registration #3	2012-11-15	23.004 mi
Registration #4	2013-11-14	26.624 mi
Registration #5	2014-11-11	30.083 mi
Registration #6	2015-11-04	33.533 mi
Registration #7	2016-11-11	37.472 mi
Registration #8	2017-11-06	39.073 mi
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		11.117 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1872 mm
Height	1473 mm
Length	5076 mm
Wheel base	3035 mm
Kerb weight	1965 kg

Additional information

Fuel tank capacity	90 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	64293040419468

CarCheck.co.uk page 13/13