



report date: 2024-03-28

General information

| | |
|---------------------|---------------------------------------|
| Make | CITROEN |
| Model | DISPATCH 1000 L1H1 ENTERPRISE P/V HDI |
| Colour | Blue |
| Year of manufacture | 2015 |
| Top speed | 90 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 89 BHP |
| Max. torque | 180 Nm at 1.500 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 35.8 mpg |
| Consumption extra urban | 45.6 mpg |
| Consumption combined | 42.2 mpg |
| CO2 emission | 177 g/km |
| CO2 label | I |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-12-19 |
| Pictures | 12 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-03-29 |
| MOT pass rate | 75 % |
| MOT passed | 6 |
| Failed MOT tests | 2 |
| Total advice items | 10 |
| Total items failed | 0 |

| | |
|------------------|------------------|
| MOT #8 | 2024-03-19 16:46 |
| MOT test number | 894478697279 |
| Result | ✓ Passed |
| Next expiry date | 2025-03-29 |

| | |
|--|------------------|
| MOT #7 | 2024-03-19 14:57 |
| MOT test number | 424216533578 |
| Result | ✗ Failed |
| MAJOR Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) | |
| MAJOR Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii)) | |

| | |
|-----------------|---|
| MOT #6 | 2023-03-30 15:33 |
| MOT test number | 311342453495 |
| Result | ✓ Passed |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) |

**MOT #5** 2023-03-17 11:29**MOT test number** 537780392244**Result** ✗ Failed

- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Oil leak, but not excessive Drive shaft seal. (8.4.1 (a) (i))
- Advice** Offside Rear Brake pad(s) wearing thin Slight bind. (1.1.13 (a) (ii))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Brake pipe corroded, covered in grease or other material All four flex hoses ridged pipe ends at calipers corroded. (1.1.11 (c))
- MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Tyre slightly damaged/cracking or perishing All tyres age cracking on sides of tread. (5.2.3 (d) (ii))

MOT #4 2022-01-06 16:49**MOT test number** 486986105311**Result** ✓ Passed**MOT #3** 2020-12-29 17:07**MOT test number** 360077225488**Result** ✓ Passed**MOT #2** 2019-12-30 12:40**MOT test number** 271171072455**Result** ✓ Passed**MOT #1** 2018-12-22 10:45**MOT test number** 564962539463**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
29 March 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 April |
| Days left | 337 |
| MOT expiry date | 29 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|----------------------------------|------------|
| Vehicle class | 39 |
| Standard rate (12 months) | £ 275,00,- |
| Standard rate (6 months) | £ 151,25,- |



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this CITROEN had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 10 |
| First mileage registration | 2015-12-23 |
| Last registration | 2024-03-19 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2015-12-23 | 28 mi |
| Registration #2 | 2018-12-22 | 35.912 mi |
| Registration #3 | 2019-12-30 | 42.994 mi |
| Registration #4 | 2020-12-29 | 53.486 mi |
| Registration #5 | 2021-03-20 | 55.277 mi |
| Registration #6 | 2021-03-20 | 55.277 mi |
| Registration #7 | 2021-03-20 | 55.277 mi |
| Registration #8 | 2021-03-20 | 55.277 mi |
| Registration #9 | 2021-03-20 | 55.277 mi |
| Registration #10 | 2021-03-20 | 55.277 mi |

More info >



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1895 mm |
| Height | 1942 mm |
| Length | 4805 mm |
| Kerb weight | 1673 kg |
| Max. allowed weight | 2661 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 80 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 3 |
| Number of axles | 2 |
| Engine number | JBDF0061045 |