





report date: 2024-03-28

General information

Make	LAND ROVER
Model	FREELANDER SD4 HSE LUXURY
Colour	Black
Year of manufacture	2013
Top speed	118 mph
0 - 100 km/h	11.2 seconds
0 - 60 mph	8.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	110 kW / 150 HP / 190 BHP
Max. torque	420 Nm at 1.750 rpm
Engine capacity	2.179 сс
Cylinders	4
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	185 g/km
CO2 label	I



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2022-02-19

Pictures 5

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MM63JAG

report date: 2024-03-28

MOT history

MOT expiry date	2024-10-06
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	10
Total items failed	2

MOT #10	2023-09-28 11:57
MOT test number	113595792808
Result	✓ Passed
Next expiry date	2024-10-06

MOT #9	2023-09-28 11:57
MOT test number	230648949142
Result	× Failed
Pass with rectification	Nearside Headlamp aim too high and too far to the right. (4.1.2 (a))

MOT #8	2022-10-04 10:44
MOT test number	664593023727
Result	✓ Passed
Advice Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))	

MOT #7	2021-10-07 08:28
MOT test number	517746539067
Result	✓ Passed

CarCheck.co.uk page 3/12



Advice

MM63JAG

report date: 2024-03-28

MOT #6

MOT test number

586054038885

Result

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5 2019-11-29 09:37 **MOT** test number 695577775802 Result ✓ Passed **MOT #4** 2018-11-27 09:29 **MOT** test number 502711968498 Result ✓ Passed **Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i)) **Advice** Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))

Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT test number

Result

Pass with rectification

Nearside Headlamp aim too high (4.1.2 (a))

Advice

Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))

Advice

Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice

Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/12



MOT test number

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2016-12-15 11:14
MOT test number	881895367258
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 March
Days left	307
MOT expiry date	6 October 2024
Full MOT history	See MOT history

Tax calculation

CarCheck.co.uk page 6/12



MM63JAG

report date: 2024-03-28

Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner history		
For how long did the current and previous owner(s) have this LAND ROVER? How many o ROVER have? Check it in the premium report and see all owner registrations. Download to		

	More info >	>
Plate changes		
See in this check if this LAND ROVER had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Flate since		
	More info >	>

CarCheck.co.uk page 9/12



MM63JAG

report date: 2024-03-28

Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-12-20
Last registration	2023-09-28
Complete history	See info



2013-12-20	10 mi
2016-12-15	34.690 mi
2017-11-24	40.721 mi
2018-11-27	64.428 mi
2018-11-27	64.428 mi
2019-11-29	85.665 mi
	11.777 es
	9.70 es
	2016-12-15 2017-11-24 2018-11-27 2018-11-27

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2180 mm
Height	1740 mm
Length	4500 mm
Wheel base	2660 mm
Kerb weight	1770 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	68 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DZ784152302224DT

CarCheck.co.uk page 12/12