





report date: 2024-03-29

### General information

Make	TOYOTA
Model	RAV-4 D-4D XT3
Colour	Silver
Year of manufacture	2005
Top speed	106 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	114 BHP
Max. torque	250 Nm at 1.800 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	46.3 mpg
Consumption combined	39.8 mpg
CO2 emission	190 g/km
CO2 label	1



CarCheck.co.uk page 1/15



### Internet history

#### Entry 1

Date	2021-02-05	
Pictures	1	
Listing price	<u>View report</u>	



source: autoonline.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-29

	~-				
10/1/	TC	h		-	r\ /
1011		ш	51	LUI	l V
	•			-	. ,

MOT expiry date	2023-10-30
MOT pass rate	63 %
MOT passed	15
Failed MOT tests	9
Total advice items	27
Total items failed	21

MOT #24	2022-10-31 14:55
MOT test number	628700990999
Result	✓ Passed
Next expiry date	2023-10-30

MOT #23		2022-10-31 14:55
MOT test number		333911987914
Result		<b>X</b> Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))	

MOT #22	2021-10-07 13:42
MOT test number	787914407614
Result	✓ Passed

MOT #21		2021-10-06 14:25
MOT test	number	717166020204
Result		🗙 Failed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)	)
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
<b>Fail</b> Ne	earside Front Electrical wiring insecure and in contact with sharp edges (4.11 (a) (ii	))

page 3/15 CarCheck.co.uk



report date: 2024-03-29

MOT #20

MOT test number

925705533847

Result

Advice Underside inc suspension components corroded

MOT #19

MOT test number

Result

Fail Offside Rear Upper Coil spring fractured or broken (5.3.1 (b) (i))

Advice Underside inc suspension components corroded

MOT #18

MOT test number

S89504387524

Result

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT test number

Result

Fail Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

Fail Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

CarCheck.co.uk page 4/15



**MOT #16** 2018-04-10 09:45

**MOT test number** 386009559281

Result \( \sqrt{Passed} \)

Advice Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**Advice** Both rear tyres low, perishing and wearing inner edges slightly

**Advice** Front brake pads getting low..

**MOT #15** 2017-02-08 14:57

**MOT test number** 918688489278

**Result** ✓ Passed

MOT #14 2017-01-23 14:44

**MOT test number** 880123507523

Result X Failed

**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Fail** Nearside Rear Brake back plate(s) securing device excessively deteriorated (3.5.1j)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Fail** Offside Front Brake back plate(s) securing device excessively deteriorated (3.5.1j)

**Fail** Offside Rear Brake back plate(s) securing device excessively deteriorated (3.5.1j)

**MOT #13** 2016-07-06 11:22

**MOT test number** 421187671771

CarCheck.co.uk page 5/15



report date: 2024-03-29

**MOT #12** 2016-07-05 15:19 **MOT** test number 301714013590 Result × Failed Fail Nearside Rear Brake pipe excessively corroded front to rear (3.6.B.2c) Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2) Nearside Front Brake pipe excessively corroded (3.6.B.2c) Fail Offside Rear Brake pipe excessively corroded front to rear (3.6.B.2c) Fail Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT test number

Result

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #10 2014-07-07 15:25

MOT test number 336438384123

Result ✓ Passed

MOT test number

858277863228

Result

Advice Offside Inner Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Inner Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 6/15



report date: 2024-03-29

**MOT #8** 2013-09-23 16:03 457896463228 **MOT** test number Result × Failed **Advice** Rear Brake pad(s) wearing thin (3.5.1g) **Advice** Offside Inner Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Offside Rear coil spring broken (2.4.C.1a) Fail **Advice** Nearside Inner Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) **Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Nearside Rear coil spring broken (2.4.C.1a) Fail

MOT #7		2012-09-25 14:23
MOT test	number	499399962295
Result		<b>✓</b> Passed
Advice	Nearside Front Brake pipe slightly corroded (3.6.B.2c)	
Advice	Offside Brake pipe slightly corroded (3.6.B.2c)	
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Nearside Brake pipe slightly corroded (3.6.B.2c)	
Advice	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)	

MOT #6	2011-09-22 12:34
MOT test number	467075961205
Result	<b>✓</b> Passed
Notice Front brake discs heavily corroded	

CarCheck.co.uk page 7/15



MOT #5 2011-09-22 12:34

**MOT test number** 258895961256

**Result** X Failed

**Notice** Front brake discs heavily corroded

Pass with rectification Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #4 2010-09-27 13:35

**MOT test number** 930480670230

**Result** ✓ Passed

MOT #3 2009-09-16 10:40

**MOT test number** 244799359217

Result \rightarrow Passed

**MOT #2** 2009-09-16 10:40

**MOT test number** 183019759229

**Result** X Failed

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #1** 2008-09-24 09:16

**MOT test number** 900398868289

**Result** ✓ Passed

CarCheck.co.uk page 8/15



#### Tax & MOT check



MOT

Expired:
30 October 2023

Tax expired: 30 August 2023

**Tax status** 

Expired at 30 August 2023

Days left 243 days too late

MOT expiry date 30 October 2023

Full MOT history See MOT history

#### Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 9/15



report date: 2024-03-29

#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



#### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 11/15



### Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
manage and a second sec	
***************************************	
THE STREET STREET	
********	
***************************************	
THE STREET STREET	
	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Correct registration	NK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 12/15



#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 13/15



### Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-09-26
Last registration	2022-10-31
Complete history	See info



Registration #1	2005-09-26	13 mi
Registration #2	2008-09-24	33.154 mi
Registration #3	2009-09-16	37.974 mi
Registration #4	2010-09-27	42.697 mi
Registration #5	2011-09-22	46.628 mi
Registration #6	2012-09-25	50.030 mi
Registration #7	2013-09-23	52.397 mi
Registration #8	2013-09-24	52.397 mi
Registration #9	2014-07-07	52.944 mi
Registration #10	2015-07-06	61.427 mi
Registration #11	2016-07-05	68.688 mi
Registration #12	2016-07-06	68.689 mi
Registration #13		11.117 es
Registration #14		71.777 es
Registration #15		11.777 mi
Registration #16		71.777 es
Registration #17		71.777 es
Registration #18		11.777 es
Registration #19		11.117 es
Registration #20		71.777 es
Registration #21		71,777 66
Registration #22		11.777 es
Registration #23		11.777 es
Registration #24		11.777 es

More info >



Car features

S0225	Air conditioning
50295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1785 mm
Height	1710 mm
Length	4260 mm
Wheel base	2490 mm
Kerb weight	1490 kg
Max. allowed weight	1930 kg

# Additional information

Fuel tank capacity	57 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 15/1

Number of axles 2

Engine number 1CD0491619