





report date: 2024-03-29

General information

Make	LAND ROVER
Model	FREELANDER SD4 HSE LUXURY
Colour	White
Year of manufacture	2013
Top speed	118 mph
0 - 100 km/h	11.2 seconds
0 - 60 mph	8.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	110 kW / 150 HP / 190 BHP
Max. torque	420 Nm at 1.750 rpm
Engine capacity	2.179 сс
Cylinders	4
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	185 g/km
CO2 label	I



CarCheck.co.uk page 1/12



Internet history


Entry 1

Date 2021-10-05

Pictures 10

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-09-22
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	13
Total items failed	10

MOT #11	2023-09-21 15:44
MOT test number	990303403423
Result	✓ Passed
Next expiry date	2024-09-22
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	ı

MOT #10	2023-09-15 14:17
MOT test number	172603716227
Result	X Failed
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a	a) (ii))
Fail Offside Rear Anti-roll bar linkage insecure and impairing directional stability (5.3	.3 (a) (ii))
Fail Offside Front Brake hose excessively chafed (1.1.12 (b) (ii))	
Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #9	2022-09-22 14:16
MOT test number	112441721867
Result	✓ Passed
Advice Rear Oil leak, but not excessive diff. (8.4.1 (a) (i))	

CarCheck.co.uk page 3/12



MOT #8 2022-09-15 14:39

MOT test number 238189098725

Result X Failed

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm 235/55-19. (5.2.3 (e))

Fail Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Rear Oil leak, but not excessive diff. (8.4.1 (a) (i))

Fail Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #7 2021-09-11 08:30

MOT test number 817028501107

Result \(\sqrt{Passed} \)

Advice Tyre worn close to legal limit/worn on edge Both front (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6 2020-09-05 11:03

MOT test number 525172373348

Result

Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Play in steering rack inner joint(s)

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5 2019-09-23 13:43

MOT test number 837767789905

Result
✓ Passed

CarCheck.co.uk page 4/12



NL63YVT

report date: 2024-03-29

MOT #4 2018-12-06 09:34

MOT test number 647042903953

MOT #3 2017-12-01 14:50

MOT test number 400304410118

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #2 2016-11-30 15:20

MOT test number 784760091543

Result \rightarrow Passed

MOT #1 2016-11-30 14:13

MOT test number 118054709928

Result X Failed

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Registration plate lamp not working (1.1.C.1d)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/12



Tax & MOT check





Expires: 22 September 2024

Tax status	Valid until 1 December
Days left	217
MOT expiry date	22 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 6/12



Damage history


Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date	
Category	
Туре	

Damage 2

Damage 2	
Date	
Category	



Extra LAND ROVER salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e when miscory	
For how long did the current and previous owner(s) have this LAND ROVER? How many o ROVER have? Check it in the premium report and see all owner registrations. Download to	

THE PERSON NAMED IN COLUMN TO THE PE	
	More info >
Plate changes	
See in this check if this LAND ROVER had different number plates.	
Number of plates	,
Current registration	UK ZIS
Plate since	
Current registration	RIV.
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-12-06
Last registration	2023-09-21
Complete history	See info



Registration #1	2013-12-06	8 mi
Registration #2	2016-11-30	41.645 mi
Registration #3	2016-11-30	41.645 mi
Registration #4	2017-12-01	55.152 mi
Registration #5	2018-12-06	63.253 mi
Registration #6	2019-09-23	70.701 mi
Registration #7	2020-09-05	95.574 mi
Registration #8		11.777 ea
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.177 ms
Registration #12		11.777 mg
Registration #13		D.777 es

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****

Video <u>see crash video</u>



Dimensions & weight

Width	2180 mm
Height	1740 mm
Length	4500 mm
Wheel base	2660 mm
Kerb weight	1770 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	68 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DZ784152302224DT

CarCheck.co.uk page 12/12