



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	EOS GTI EDITION30 T 230
Colour	Silver
Year of manufacture	2007
Top speed	150 mph
0 - 60 mph	6.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	227 BHP
Max. torque	300 Nm at 2.200 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.4 mpg
CO2 emission	194 g/km
CO2 label	J






Internet history

Entry 3


Date	2023-06-07
Pictures	35
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 2

Date	2021-09-19
Pictures	22
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

Entry 1

Date	2021-07-30
Pictures	0
Listing price	<a href="#">View report</a>

source: autotrader.co.uk

**MOT history**

<b>MOT expiry date</b>	2024-05-12
<b>MOT pass rate</b>	93 %
<b>MOT passed</b>	14
<b>Failed MOT tests</b>	1
<b>Total advice items</b>	10
<b>Total items failed</b>	5

**MOT #15** 2023-05-13 12:16**MOT test number** 464819633637**Result** Passed**Next expiry date** 2024-05-12

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2023-05-08 13:05**MOT test number** 524361754670**Result** Failed

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt Nearside & Offside (5.3.4 (b) (ii))
- Fail** Offside Rear Parking (secondary brake) on a single line braking system has no recorded effort at a wheel (1.3.1 (a) (ii))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #13** 2022-03-01 08:08**MOT test number** 645848229163**Result** ✓ Passed**Minor** Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #12** 2021-02-09 13:26**MOT test number** 680567667971**Result** ✓ Passed**MOT #11** 2020-02-20 14:12**MOT test number** 703479855741**Result** ✓ Passed**MOT #10** 2019-02-27 15:04**MOT test number** 582861122209**Result** ✓ Passed**MOT #9** 2018-03-20 15:27**MOT test number** 502578691319**Result** ✓ Passed**MOT #8** 2017-03-16 17:15**MOT test number** 290627817019**Result** ✓ Passed**MOT #7** 2016-03-02 11:25**MOT test number** 763567212935**Result** ✓ Passed



<b>MOT #6</b>	2015-03-26 16:40
---------------	------------------

<b>MOT test number</b>	208595185076
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #5</b>	2014-03-13 11:38
---------------	------------------

<b>MOT test number</b>	127052074028
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2013-03-28 16:18
---------------	------------------

<b>MOT test number</b>	407037383054
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2012-09-18 16:25
---------------	------------------

<b>MOT test number</b>	176172162292
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2011-08-15 12:39
---------------	------------------

<b>MOT test number</b>	435917421220
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
---------------	---

<b>Advice</b>	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
---------------	--

<b>MOT #1</b>	2010-08-24 12:27
---------------	------------------

<b>MOT test number</b>	211346430253
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 June 2024

✓  
**MOT**  
  
Expires:  
12 May 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	12 May 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>AY57WUG</b>
Plate since	2024-03-29
Current registration	 <b>AY57WUG</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-09-01
Last registration	2023-05-13
Complete history	<a href="#">See info</a>



Registration #1	2007-09-01	13 mi
Registration #2	2010-08-24	6.351 mi
Registration #3	2011-08-15	14.420 mi
Registration #4	2012-09-18	23.246 mi
Registration #5	2013-03-28	25.099 mi
Registration #6	2014-03-13	26.212 mi
Registration #7	2015-03-26	29.027 mi
Registration #8	2016-03-02	33.428 mi
Registration #9	2017-03-16	37.893 mi
Registration #10	2018-03-20	41.132 mi
Registration #11	2019-03-20	45.377 mi
Registration #12	2020-03-20	49.622 mi
Registration #13	2021-03-20	53.867 mi
Registration #14	2022-03-20	58.112 mi
Registration #15	2023-03-20	62.357 mi
Registration #16	2024-03-20	66.602 mi
Registration #17	2025-03-20	70.847 mi
Registration #18	2026-03-20	75.092 mi
Registration #19	2027-03-20	79.337 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1469 mm
Length	4216 mm
Wheel base	2578 mm
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

**Number of axles**

2

**Engine number**

NOT KNOWN