



L44HTT


report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | AUDI |
| Model | TT V6 QUATTRO |
| Colour | Silver |
| Year of manufacture | 2007 |
| Top speed | 155 mph |
| 0 - 60 mph | 5.9 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 250 BHP |
| Max. torque | 320 Nm at 2.500 rpm |
| Engine capacity | 3.189 cc |
| Cylinders | 6 |
| Fuel type | Petrol |
| Consumption city | 19.2 mpg |
| Consumption extra urban | 36.2 mpg |
| Consumption combined | 27.4 mpg |
| CO2 emission | 247 g/km |
| CO2 label | L |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-01-28 |
| Pictures | 10 |
| Listing price | View report |



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-03-14 |
| MOT pass rate | 78 % |
| MOT passed | 14 |
| Failed MOT tests | 4 |
| Total advice items | 23 |
| Total items failed | 8 |

MOT #18 2024-03-08 18:48

MOT test number 684898956753

Result ✓ Passed

Next expiry date 2025-03-14

- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17 2023-03-08 16:58

MOT test number 159454056935

Result ✓ Passed

- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Bald on inner facing edge. (5.2.3 (e))
- Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Bald on inner facing edge. (5.2.3 (e))

**MOT #16**

2022-02-28 17:52

MOT test number

716982162781

Result

✓ Passed

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #15**

2022-02-22 12:06

MOT test number

493563009832

Result

✗ Failed

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Front Exhaust has a major leak of exhaust gases (6.1.2 (a))**MOT #14**

2021-03-15 14:13

MOT test number

220354564784

Result

✓ Passed

Advice Front Tyre worn close to legal limit/worn on edge Both front tyres worn on edges (5.2.3 (e))**MOT #13**

2021-03-15 14:13

MOT test number

583415807720

Result

✗ Failed

Pass with rectification Rear Registration plate does not conform to the specified requirements (0.1 (d))**Advice** Front Tyre worn close to legal limit/worn on edge Both front tyres worn on edges (5.2.3 (e))**Pass with rectification** Front Registration plate does not conform to the specified requirements (0.1 (d))

**MOT #12** 2019-05-14 15:46**MOT test number** 270822520101**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #11** 2018-06-01 10:23**MOT test number** 692298898102**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #10** 2018-06-01 09:26**MOT test number** 109431385176**Result** ✗ Failed**Fail** Rear Registration plate does not conform to the specified requirements (0.1 (d))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Front Registration plate does not conform to the specified requirements (0.1 (d))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #9** 2017-05-25 11:56**MOT test number** 224936041041**Result** ✓ Passed**MOT #8** 2016-05-28 08:15**MOT test number** 801004726226**Result** ✓ Passed



| | |
|------------------------|--|
| MOT #7 | 2015-08-11 13:11 |
| MOT test number | 958433825281 |
| Result | ✓ Passed |
| MOT #6 | 2014-08-02 11:36 |
| MOT test number | 946924414258 |
| Result | ✓ Passed |
| MOT #5 | 2013-08-02 14:27 |
| MOT test number | 936084613224 |
| Result | ✓ Passed |
| MOT #4 | 2012-04-11 14:16 |
| MOT test number | 318782102116 |
| Result | ✓ Passed |
| MOT #3 | 2012-04-07 12:31 |
| MOT test number | 417878092060 |
| Result | ✗ Failed |
| Fail | Offside Front Front position lamp(s) not working (1.1.A.3b) |
| Fail | Nearside Front Front position lamp(s) not working (1.1.A.3b) |
| Notice | Advise puncture to o/s/r |
| MOT #2 | 2011-05-06 12:54 |
| MOT test number | 139206421194 |
| Result | ✓ Passed |
| MOT #1 | 2010-06-22 15:26 |
| MOT test number | 614803470146 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
14 March 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 September |
| Days left | 126 |
| MOT expiry date | 14 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | L |
| Single payment (12 months) | £ 675,00,- |
| Single six month payment | £ 371,25,- |
| Total payable by 12 monthly instalments | £ 708,75,- |




Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this AUDI had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2019-03-28 |
| Current registration | |
| Plate since | 2019-03-28 |

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 20 |
| First mileage registration | 2007-09-01 |
| Last registration | 2024-03-08 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2007-09-01 | 15 mi |
| Registration #2 | 2010-06-22 | 37.169 mi |
| Registration #3 | 2011-05-06 | 47.243 mi |
| Registration #4 | 2012-04-07 | 53.001 mi |
| Registration #5 | 2012-04-11 | 53.001 mi |
| Registration #6 | 2013-08-02 | 68.281 mi |
| Registration #7 | 2014-08-02 | 78.254 mi |
| Registration #8 | 2015-08-11 | 84.200 mi |
| Registration #9 | 2016-05-28 | 85.630 mi |
| Registration #10 | 2017-05-25 | 96.051 mi |
| Registration #11 | 2018-05-25 | 101.277 mi |
| Registration #12 | 2019-05-25 | 101.277 mi |
| Registration #13 | 2020-05-25 | 101.277 mi |
| Registration #14 | 2021-05-25 | 101.277 mi |
| Registration #15 | 2022-05-25 | 101.277 mi |
| Registration #16 | 2023-05-25 | 101.277 mi |
| Registration #17 | 2024-03-08 | 101.277 mi |
| Registration #18 | | |
| Registration #19 | | |
| Registration #20 | | |

More info >



Car features

The AUDI factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1842 mm |
| Height | 1352 mm |
| Length | 4178 mm |
| Wheel base | 2468 mm |
| Kerb weight | 1410 kg |
| Max. allowed weight | 1810 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 2 |
| Number of seats | 4 |

| | |
|------------------------|------------|
| Number of axles | 2 |
| Engine number | BUB 026650 |