



RENAULT

EA59LPY

report date: 2024-03-28

General information

Make	RENAULT
Model	KANGOO ML20 DCI
Colour	White
Year of manufacture	-
Top speed	91 mph
0 - 60 mph	19.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Max. torque	185 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	57.6 mpg
Consumption combined	54.3 mpg





MOT history

MOT #15 2021-10-27 09:14

MOT test number 967990812812

Result ✓ Passed

Next expiry date 2022-10-26

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #14**

2021-10-21 16:17

**MOT test number**

974565961963

**Result****✗ Failed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- MAJOR** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))
- MAJOR** Front Brakes imbalanced across an axle (1.2.1 (b) (i))
- MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- MAJOR** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Rear Brake binding
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #13**

2020-09-29 09:26

**MOT test number**

246439674423

**Result****✓ Passed**

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #12** 2019-10-16 12:31**MOT test number** 563372060293**Result** ✓ Passed

- Advice** Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Play in steering rack inner joint(s)
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #11** 2018-09-29 08:23**MOT test number** 522615071410**Result** ✓ Passed

- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #10** 2017-10-07 08:20**MOT test number** 168759257022**Result** ✓ Passed**MOT #9** 2016-10-14 17:02**MOT test number** 202055770233**Result** ✓ Passed

**MOT #8** 2016-10-13 15:08**MOT test number** 363719703407**Result** ✗ Failed**Fail** Nearside Rear brake disc modified and seriously weakened (3.5.1n)**Fail** Rear Brake pipe excessively corroded (3.6.B.2c)**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**MOT #7** 2015-09-24 15:43**MOT test number** 224799822560**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Ball joint has slight play inner rack end (2.2.B.1f)**MOT #6** 2015-09-24 15:43**MOT test number** 517862438495**Result** ✗ Failed**Pass with rectification** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Ball joint has slight play inner rack end (2.2.B.1f)**MOT #5** 2014-10-02 10:55**MOT test number** 289245774293**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #4** 2014-09-29 14:22**MOT test number** 347342674280**Result** ✗ Failed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2013-10-19 08:59**MOT test number** 518032093227**Result** ✓ Passed**MOT #2** 2012-10-24 10:07**MOT test number** 589578792259**Result** ✓ Passed**MOT #1** 2012-10-22 09:21**MOT test number** 488596192295**Result** ✗ Failed**Notice** Front wipers split**Fail** Offside Front Headlamp insecure (1.7.3)**Fail** Offside Front Headlamp aim too high (1.8)



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-10-23
Last registration	2021-10-27
Complete history	<a href="#">See info</a>



Registration #1	2009-10-23	27 mi
Registration #2	2012-10-22	40.863 mi
Registration #3	2012-10-24	40.863 mi
Registration #4	2013-10-19	52.831 mi
Registration #5	2014-09-29	61.440 mi
Registration #6	2014-10-02	61.450 mi
Registration #7	2015-09-24	68.271 mi
Registration #8	2015-09-24	68.271 mi
Registration #9	2016-09-24	75.277 mi
Registration #10	2016-09-24	75.277 mi
Registration #11	2016-09-24	75.277 mi
Registration #12	2016-09-24	75.277 mi
Registration #13	2016-09-24	75.277 mi
Registration #14	2016-09-24	75.277 mi
Registration #15	2016-09-24	75.277 mi
Registration #16	2021-10-27	75.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1829 mm
Height	1844 mm
Length	4213 mm
Kerb weight	1277 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	D030301