



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D DRIVE SE
Colour	Silver
Year of manufacture	2012
Top speed	121 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	6.6 mpg
CO2 emission	99 g/km
CO2 label	A






Internet history

Entry 2

Date	2021-07-24
Pictures	20
Listing price	View report



source: yesauto.com

Entry 1

Date	2021-07-21
Pictures	21
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-01
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	8
Total items failed	5

MOT #13	2023-08-02 14:06
MOT test number	978086768221
Result	✓ Passed
Next expiry date	2024-08-01
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #12	2022-08-01 11:19
MOT test number	233413843908
Result	✓ Passed
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #11	2021-08-02 15:44
MOT test number	107991942187
Result	✓ Passed

MOT #10	2021-03-30 15:27
MOT test number	539864731952
Result	✓ Passed

**MOT #9** 2021-03-29 09:30**MOT test number** 867026858734**Result** ✗ Failed**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #8** 2020-03-17 12:56**MOT test number** 524909601800**Result** ✓ Passed**MOT #7** 2020-03-16 09:10**MOT test number** 435338738291**Result** ✗ Failed**Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt split (6.1.7 (g) (ii))**MOT #6** 2019-04-02 16:09**MOT test number** 529816569360**Result** ✓ Passed**Advice** Covers fitted to underside of vehicle preventing inspection of some components

**MOT #5** 2019-04-01 10:58**MOT test number** 628614643352**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Covers fitted to underside of vehicle preventing inspection of some components**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Position lamp not working (4.2.1 (a))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #4** 2018-03-30 09:04**MOT test number** 769349663937**Result** ✓ Passed**Advice** Uneven wear on both rear tyres**MOT #3** 2017-04-03 08:08**MOT test number** 349277162649**Result** ✓ Passed**MOT #2** 2016-03-30 08:05**MOT test number** 917338099331**Result** ✓ Passed**MOT #1** 2015-04-03 08:50**MOT test number** 686843395006**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
1 August 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	1 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-04-05
Last registration	2023-08-02
Complete history	See info



Registration #1	2012-04-05	15 mi
Registration #2	2015-04-03	17.739 mi
Registration #3	2016-03-30	23.857 mi
Registration #4	2017-04-03	31.685 mi
Registration #5	2018-03-30	39.121 mi
Registration #6	2019-04-01	47.925 mi
Registration #7	2019-04-02	47.931 mi
Registration #8	2020-03-16	57.208 mi
Registration #9	2020-03-16	57.208 mi
Registration #10	2020-03-16	57.208 mi
Registration #11	2020-03-16	57.208 mi
Registration #12	2020-03-16	57.208 mi
Registration #13	2020-03-16	57.208 mi
Registration #14	2020-03-16	57.208 mi
Registration #15	2020-03-16	57.208 mi
Registration #16	2020-03-16	57.208 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1433 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2041867