





report date: 2024-03-28

General information

Make	MINI
Model	ONE
Colour	Blue
Year of manufacture	2015
Top speed	121 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	101 BHP
Max. torque	180 Nm at 1.400 rpm
Engine capacity	1.198 сс
Cylinders	3
Fuel type	Petrol
Consumption city	49.6 mpg
Consumption extra urban	70.6 mpg
Consumption combined	61.4 mpg
CO2 emission	108 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

Date	2021-05-21	
Pictures	1	
Listing price	View report	



source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-03-03
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	8
Total items failed	1

MOT #8	2024-03-04 08:55
MOT test number	476838277651
Result	✓ Passed
Next expiry date	2025-03-03

MOT #7		2023-05-15 14:19
MOT test	number	716082792954
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Nail in tyre	

MOT #6	2022-05-14 08:03
MOT test number	176562307519
Result	✓ Passed
Advice Oil leak, but not excessive back of engine bay (8.4.1 (a) (i))	

MOT #5	2021-05-18 14:04
MOT test number	123036944237
Result	✓ Passed

CarCheck.co.uk page 3/11



MOT #4

Advice

Result

Fail

PE65CMZ

report date: 2024-03-28

2020-09-16 13:35

× Failed

MOT test number 966825976383

Tyre worn close to legal limit/worn on edge Both front tyres wearing on edges (5.2.3 (e))

MOT #3 2020-09-16 11:01

MOT test number 338760123076

Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice Tyre worn close to legal limit/worn on edge Both front tyres wearing on edges (5.2.3 (e))

MOT #2 2019-09-13 11:05

MOT test number 983572395241

Result ✓ Passed

MOT #1 2018-09-21 09:31

MOT test number 617233480884

Result ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	3 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

$\hat{}$	
()Whor	hictory
OWILL	11151 OT V
Owner	,

		_
For how long did the current and previous owner(s) have this MINI? How many owners d Check it in the premium report and see all owner registrations. Download the full report		

	More info >	
Plate changes		
See in this check if this MINI had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	NK SIE	
Plate since		
	More info >	

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0111.5	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-09-01
Last registration	2024-03-04
Complete history	See info



Registration #1	2015-09-01	29 mi
Registration #2	2018-09-21	22.739 mi
Registration #3	2019-09-13	35.438 mi
Registration #4	2020-09-16	52.239 mi
Registration #5	2020-09-16	52.239 mi
Registration #6		11.777 es
Registration #6 Registration #7		11.777 ea
-		1.77 m
Registration #7		11.77 es 11.77 es 11.77 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1727 mm
Height	1414 mm
Length	3821 mm
Wheel base	2495 mm
Kerb weight	1090 kg
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	40
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 11/1:

Number of axles2Engine numberF3421087