





report date: 2024-03-28

General information

Make	JAGUAR
Model	XF R-SPORT
Colour	White
Year of manufacture	2017
Top speed	140 mph
0 - 60 mph	7.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	177 BHP
Max. torque	430 Nm at 1.750 rpm
Engine capacity	1.999 сс
Cylinders	4
Fuel type	Diesel
Consumption city	56.5 mpg
Consumption extra urban	76.4 mpg
Consumption combined	67.3 mpg
CO2 emission	109 g/km
CO2 label	В



CarCheck.co.uk page 1/11



Internet history

Emter.	1
	ъ.

LIICI Y I	
Date	2021-08-06
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-07-07
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	11
Total items failed	3

MOT #7	2023-07-03 10:42
MOT test number	188933086480
Result	✓ Passed
Next expiry date	2024-07-07

MOT #6	2022-07-08 14:12
MOT test number	671176978868
Result	✓ Passed
Advice Offside Rear Brake pipe slightly damaged (1.1.11 (c))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #5	2021-06-14 15:27
MOT test number	265002670899
Result	✓ Passed
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/11



MOT #4 2021-06-09 08:58

MOT test number 473823748453

Result X Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened discs inner faces outer edge area (1.1.14 (a) (ii))

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords in tread and can see cords (5.2.3 (d) (i))

Advice Nearside Front Tyre slightly damaged/cracking or perishing strongly advise (5.2.3 (d) (ii))

Fail Brake pedal anti-slip provision missing (1.1.2 (c))

MOT #3 2020-08-20 10:10

MOT test number 700515748416

Result \(\sqrt{Passed} \)

Advice Offside Front Tyre slightly damaged/cracking or perishing sidewalls inner and outer (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing sidewalls inner and outer (5.2.3 (d) (ii))

MOT #2 2020-08-20 09:34

MOT test number 517384484486

Result X Failed

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing sidewalls inner and outer (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing sidewalls inner and outer (5.2.3 (d) (ii))

MOT #1 2020-06-27 05:11

MOT test number 558582628038

Result
✓ Passed

Advice COVID-19 6 MONTH EXTENSION

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	7 July 2024
Full MOT history	See MOT history

Tax calculation

1 10 10 10 1	
Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

o milet mestery	
For how long did the current and previous owner(s) have this JAGUAR? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	,
Current registration	OK STE
Plate since	
Current registration	AIR AIR
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-07-05
Last registration	2023-07-03
Complete history	See info



Registration #1	2017-07-05	17 mi
Registration #2	2020-08-20	25.442 mi
Registration #3	2020-08-20	25.442 mi
Registration #4	2021-06-09	30.974 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		n.m.

More info >

CarCheck.co.uk page 10/11



Safety ratings

NCAP rating	****
Adult	92%
Children	82%
Pedestrian	81%
Safety systems	82%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	2075 mm
Height	1416 mm
Length	4672 mm
Wheel base	2835 mm
Kerb weight	1550 kg
Max. allowed weight	2135 kg

Additional information

Fuel tank capacity	56 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	170307W0834204DTD

CarCheck.co.uk page 11/11