




report date: 2024-03-29

General information

Make	AUDI
Model	A4 AVANT TDI DPF SE
Colour	Red
Year of manufacture	2009
Top speed	125 mph
Gearbox	8 speed CVT

Engine & fuel consumption

Power	143 BHP
Max. torque	320 Nm at 2.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	155 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-01-27
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-01-24
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	68
Total items failed	8

MOT #17	2023-01-25 12:42
MOT test number	738680064011
Result	✓ Passed
Next expiry date	2024-01-24
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2021-11-17 14:38
MOT test number	912446899699
Result	✓ Passed

MOT #15	2021-11-17 12:56
MOT test number	290459646049
Result	✗ Failed
MAJOR	Central Rear Seat belt buckle not functioning as intended (7.1.2 (d))

MOT #14	2020-10-21 11:07
MOT test number	746537364018
Result	✓ Passed
Advice	Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement X2. (5.3.4 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement X2. (5.3.4 (a) (i))

**MOT #13**

2019-10-23 08:34

MOT test number

113439966657

Result

✓ Passed

Advice Central Exhaust silencer slightly loose Exhaust clamp corroded and broken. (8.1.1 (b) (i))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #12**

2019-10-23 08:34

MOT test number

358199482238

Result

✗ Failed

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Central Exhaust silencer slightly loose Exhaust clamp corroded and broken. (8.1.1 (b) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))



MOT #11

2018-11-01 16:45

MOT test number

174718367086

Result

✓ Passed

- Advice

Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice

Front Front Register plate deteriorated
- Advice

Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear Arm (5.3.4 (a) (i))
- Advice

Rear Tyre's Deformed
- Advice

Rear Coil spring corroded (5.3.1 (b) (i))
- Advice

Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear Arm (5.3.4 (a) (i))
- Advice

Offside Front wiper smears
- Advice

Rear Bumper Damaged



MOT #10

2018-10-31 09:39

MOT test number

685432392088

Result

✗ Failed

- Advice

Rear Coil spring corroded (5.3.1 (b) (i))
- Advice

Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear Arm (5.3.4 (a) (i))
- DANGEROUS

Offside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice

Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice

Offside Front wiper smears
- Advice

Rear Bumper Damaged
- Advice

Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice

Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear Arm (5.3.4 (a) (i))
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Front Front Register plate deteriorated
- Advice

Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice

Rear Tyre's Deformed



MOT #9

2017-10-31 16:10

MOT test number

290520647939

Result

✓ Passed

- Advice

Nearside Front Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement both (2.4.G.2)
- Advice

Fuel flap requires emergency release cord to open
- Advice

Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice

Rear tyres slightly deformed
- Advice

Front registration plate deteriorated but not likely to be misread recommend replace (6.3.1d)
- Advice

Offside Front Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement both (2.4.G.2)
- Advice

Offside Front Shock absorber has a light misting of oil (2.7.3)
- Advice

Front wipers smear screen

**MOT #8**

2017-10-30 10:13

MOT test number

471301452807

Result**✗ Failed**

- Advice** Front wipers smear screen
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Front registration plate deteriorated but not likely to be misread recommend replace (6.3.1d)
- Advice** Fuel flap requires emergency release cord to open
- Advice** Offside Front Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement both (2.4.G.2)
- Advice** Rear tyres slightly deformed
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement both (2.4.G.2)

MOT #7

2016-11-17 17:04

MOT test number

129677533430

Result**✓ Passed**

- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Front Shock absorber has a light misting of oil both (2.7.3)

**MOT #6**

2016-11-17 13:33

MOT test number

614652505840

Result**✗ Failed**

- Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Front Shock absorber has a light misting of oil both fronts (2.7.3)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)

MOT #5

2016-11-17 10:55

MOT test number

678829615035

Result**✗ Failed**

- Advice** Nearside Rear Nail in tyre
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Front Shock absorber has a light misting of oil both fronts (2.7.3)
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #4** 2015-11-17 16:44**MOT test number** 844152625401**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2014-11-13 10:38**MOT test number** 447487314334**Result** ✓ Passed**MOT #2** 2013-08-08 12:07**MOT test number** 767570523224**Result** ✓ Passed**Notice** Emissions not tested due to low level of metered smoke (too clean)**MOT #1** 2012-08-17 14:34**MOT test number** 906830332268**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
1 March 2024

✕
MOT

Expired:
24 January 2024

Tax status	Expired at 1 March 2024
Days left	59 days too late
MOT expiry date	24 January 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	DU59LJJ
Plate since	2019-03-29
Current registration	DU59LJJ
Plate since	2019-03-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-09-01
Last registration	2023-01-25
Complete history	See info



Registration #1	2009-09-01	14 mi
Registration #2	2012-08-17	41.259 mi
Registration #3	2013-08-08	51.019 mi
Registration #4	2014-11-13	62.800 mi
Registration #5	2015-11-17	71.788 mi
Registration #6	2016-11-17	86.996 mi
Registration #7	2016-11-17	86.996 mi
Registration #8	2016-11-17	86.996 mi
Registration #9	2017-10-30	92.639 mi
Registration #10	2017-10-31	92.639 mi
Registration #11	2019-05-29	95.377 mi
Registration #12	2019-05-29	95.377 mi
Registration #13	2019-05-29	95.377 mi
Registration #14	2019-05-29	95.377 mi
Registration #15	2019-05-29	95.377 mi
Registration #16	2019-05-29	95.377 mi
Registration #17	2019-05-29	95.377 mi
Registration #18	2019-05-29	95.377 mi
Registration #19	2019-05-29	95.377 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1826 mm
Height	1436 mm
Length	4703 mm
Wheel base	2808 mm
Kerb weight	1555 kg
Max. allowed weight	2125 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	CAG 204562