





report date: 2024-03-28

General information

Make	PEUGEOT
Model	PARTNER HDI TEPEE OUTDOOR
Colour	Red
Year of manufacture	2010
Top speed	100 mph
0 - 60 mph	15.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	56.5 mpg
Consumption combined	49.6 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/12



Internet history

	-	-	-	-	1
ᆮ	п	ıL	г١	,	1

Life y 1	
Date	2021-02-03
Pictures	0
Listing price	View report

source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-07-27
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	20
Total items failed	4

MOT #12	2023-07-25 13:01
MOT test number	936161157515
Result	✓ Passed
Next expiry date	2024-07-27
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting (5.3.4 (a) (i))	in excessive movement
Advice Nearside Front Lower Suspension arm pin or bush worn but not resultin (5.3.4 (a) (i))	ng in excessive movement

MOT #11	2023-07-25 09:09
MOT test number	627248037782
Result	× Failed
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting (5.3.4 (a) (i))	in excessive movement
Advice Offside Front Day time running light not working	
Fail Windscreen washer not working (3.5 (a))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in (5.3.4 (a) (i))	n excessive movement

CarCheck.co.uk page 3/12



Advice

SF60JDJ

report date: 2024-03-28

MOT #10

MOT test number

257265044977

Result

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #9

MOT test number

Result

Advice

Brake pipe corroded, covered in grease or other material both front to rear (1.1.11 (c))

Advice

Rear seats folded at time of test

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Multiple chips on screen

Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Under engine cover fitted

MOT #8 2021-07-20 11:42

MOT test number 811384943564

Result X Failed

Advice Multiple chips on screen

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Under engine cover fitted

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Brake pipe corroded, covered in grease or other material both front to rear (1.1.11 (c))

Advice Rear seats folded at time of test

Fail Rear Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))

CarCheck.co.uk page 4/12



SF60JDJ

report	date:	2024-	03-28

MOT #7	2019-12-09 14:21
MOT test number	521110192617
Result	✓ Passed
MOT #6	2019-05-28 10:15
MOT test number	865191909262
Result	✓ Passed
MOT #5	2018-06-05 09:02
MOT test number	471856207442
Result	✓ Passed
MOT #4	2017-08-29 14:33
MOT test number	516101382090
Result	✓ Passed
Advice Offside Rear Tyre perished	
MOT #3	2015-10-09 09:25
MOT test number	390437111803
Result	✓ Passed
MOT #2	2014-10-10 11:37
MOT test number	266423084252
Result	✓ Passed
Result	√ rasseu
MOT #1	2013-11-08 11:26
MOT test number	899362913361
Result	✓ Passed
	•

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 December
Days left	215
MOT expiry date	27 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e when miscory		
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		GEOT
THE PARTY OF THE P		

	More info	>
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-12-20
Last registration	2023-07-25
Complete history	See info



Registration #1	2010-12-20	15 mi
Registration #2	2013-11-08	8.212 mi
Registration #3	2014-10-10	9.853 mi
Registration #4	2015-10-09	11.019 mi
Registration #5	2017-08-29	35.012 mi
Registration #6	2018-06-05	35.104 mi
Registration #7	2019-05-28	67.636 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 au
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
50295	
50482	
60501	
50566	
60567	
50569	

Dimensions & weight

Width	1810 mm
Height	1803 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1599 kg
Max. allowed weight	2040 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBBU3185836

CarCheck.co.uk page 12/12