



report date: 2024-03-29

General information

Make	MAZDA
Model	CX-7 D SPORT TECH
Colour	White
Year of manufacture	2011
Top speed	124 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	170 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.184 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	42.8 mpg
Consumption combined	37.7 mpg
CO2 emission	199 g/km
CO2 label	J





Internet history

Entry 1

Date	2022-02-20
Pictures	50
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-05
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	20
Total items failed	2

MOT #11	2023-05-26 09:43
MOT test number	516946211531
Result	✓ Passed
Next expiry date	2024-06-05
Advice	Underside of vehicle heavily corroded

MOT #10	2022-06-06 16:29
MOT test number	404229454086
Result	✓ Passed
Advice	Sub-frame corroded but not seriously weakened Front & Rear (5.3.3 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake Back Plate Missing (Bothside)

**MOT #9** 2021-11-09 12:46**MOT test number** 809966034834**Result** ✓ Passed

- Advice** Offside Rear parking brake working that well?
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Both rear and n/s/f tyres starting to wear on edges
- Advice** Front Sub-frame corroded but not seriously weakened unable to fully see due to under tray (5.3.3 (b) (i))
- Advice** All floors , sills-floors , rear brake back plate ,o/s/f under wing ,rear valance and rear cross beam all corroding
- Advice** Suspension arm corroded but not seriously weakened all rear lower (5.3.3 (b) (i))

MOT #8 2020-11-09 11:59**MOT test number** 601365809378**Result** ✓ Passed**MOT #7** 2019-10-04 10:02**MOT test number** 918352857651**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2.5mm (5.2.3 (e))
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play also rubber boot perished (5.3.4 (a) (i))

MOT #6 2018-10-09 13:11**MOT test number** 256722793021**Result** ✓ Passed

**MOT #5** 2018-06-18 06:23**MOT test number** 701058591055**Result** ✗ Failed**Fail** Offside Position lamp not working side light (4.2.1 (a))**Fail** Nearside Rear Wheel bearing has excessive play (5.1.3 (a) (i))**MOT #4** 2017-10-09 09:29**MOT test number** 194320002878**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Items removed from driver's view prior to test**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #3** 2016-10-13 08:24**MOT test number** 122616547512**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Both rear tyres at 3mm max**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2015-10-07 13:31**MOT test number** 405475869787**Result** ✓ Passed**MOT #1** 2014-09-29 11:22**MOT test number** 317162374266**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
1 January 2024

✓

MOT

Expires:
5 June 2024

Tax status	Expired at 1 January 2024
Days left	120 days too late
MOT expiry date	5 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	SV61UFG
Plate since	2024-03-29
Current registration	SV61UFG
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-09-29
Last registration	2023-05-26
Complete history	See info



Registration #1	2011-09-29	17 mi
Registration #2	2014-09-29	32.952 mi
Registration #3	2015-10-07	44.440 mi
Registration #4	2016-10-13	56.132 mi
Registration #5	2017-10-09	65.957 mi
Registration #6	2018-06-18	71.526 mi
Registration #7	2018-10-09	71.532 mi
Registration #8	2019-05-29	75.277 mi
Registration #9	2019-05-29	75.277 mi
Registration #10	2019-05-29	75.277 mi
Registration #11	2019-05-29	75.277 mi
Registration #12	2019-05-29	75.277 mi
Registration #13	2019-05-29	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	76%
Children	79%
Pedestrian	43%
Safety systems	71%
Overall rating	70%
Video	see crash video



Dimensions & weight

Width	1870 mm
Height	1645 mm
Length	4700 mm
Wheel base	2750 mm
Max. allowed weight	2430 kg

Additional information

Fuel tank capacity	69 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	R210287355