



report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI S/S
Colour	White
Year of manufacture	2014
Top speed	117 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	42.2 mpg
CO2 emission	177 g/km
CO2 label	I






Internet history

Entry 2

Date 2023-12-12

Pictures 8



source: g3remarketing.co.uk

Entry 1

Date 2021-09-20

Pictures 13

Listing price [View report](#)



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-12
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	27
Total items failed	8

MOT #11	2023-11-13 10:29
MOT test number	988454324162
Result	✓ Passed
Next expiry date	2024-11-12
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2023-11-13 10:29
MOT test number	870194037377
Result	✗ Failed
Pass with rectification	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #9	2022-10-31 09:45
MOT test number	405999807135
Result	✓ Passed
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #8** 2022-10-21 14:27**MOT test number** 426190028565**Result** ✗ Failed**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #7** 2021-11-05 16:18**MOT test number** 498544393261**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))**MOT #6** 2020-09-11 13:58**MOT test number** 320049611367**Result** ✓ Passed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2019-09-28 11:04**MOT test number** 611493484318**Result** ✓ Passed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #4**

2019-09-19 13:24

MOT test number

631418144150

Result

✗ Failed

Fail

Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Fail

Fuel system component leaking FUEL FILTER HOUSING (6.1.3 (b) (i))

Fail

Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Minor

Nearside Front Tyre obviously under inflated (5.2.3 (l))

Advice

Oil leak, but not excessive FROM ENGINE (8.4.1 (a) (i))

Minor

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice

Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Minor

Offside Front Tyre obviously under inflated (5.2.3 (l))

MOT #3

2018-09-06 11:56

MOT test number

118001075546

Result

✓ Passed

Advice

Child seat fitted

Advice

Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #2

2017-09-14 07:44

MOT test number

104689471246

Result

✓ Passed

Advice

Rear Brake pad(s) wearing thin (3.5.1g)

Advice

Nearside Rear tyre punctured

Advice

Front Brake pad(s) wearing thin (3.5.1g)



MOT #1

2017-09-09 09:30

MOT test number

766955524092

Result		✗ Failed
Fail	Nearside Front position lamp(s) not working (1.1.A.3b)	
Advice	Nearside Rear tyre punctured	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Fail	Offside Front position lamp(s) not working (1.1.A.3b)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
12 November 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	12 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	PE64WKA
Plate since	2019-06-29
Current registration	PE64WKA
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-09-19
Last registration	2023-11-13
Complete history	See info



Registration #1	2014-09-19	28 mi
Registration #2	2017-09-09	36.665 mi
Registration #3	2017-09-14	36.870 mi
Registration #4	2018-09-06	50.261 mi
Registration #5	2019-09-19	63.462 mi
Registration #6	2019-09-28	63.470 mi
Registration #7	2020-09-11	73.576 mi
Registration #8	2020-09-28	73.577 mi
Registration #9	2020-09-28	73.577 mi
Registration #10	2020-09-28	73.577 mi
Registration #11	2020-09-28	73.577 mi
Registration #12	2020-09-28	73.577 mi
Registration #13	2020-09-28	73.577 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1761 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1911 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 338109K LNQ