



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	I30 ACTIVE
Colour	Grey
Year of manufacture	2012
Top speed	113 mph
0 - 60 mph	13.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	137 Nm at 4.200 rpm
Engine capacity	1.396 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-01-31
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-08-03
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	32
Total items failed	13

MOT #13	2023-08-04 11:53
---------	------------------

MOT test number	572689681648
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-08-03
------------------	------------

- Advice** Offside Rear sill damaged.
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush. (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear arm bush. (5.3.4 (a) (i))
- Advice** Unable to open tail gate.
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush. (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear arm bush. (5.3.4 (a) (i))

**MOT #12**

2023-07-31 16:51

MOT test number

679418660335

Result**✗ Failed**

- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Nearside Rear Bumper damaged and likely to cause injury when grazed or contacted bumper damaged. (6.1.4 (a) (i))
- Fail** Nearside Rear Outer Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush. (5.3.4 (a) (i))
- Advice** No engine oil visible on dip stick prior to emissions test.(2 Litres added)
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear arm bush. (5.3.4 (a) (i))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush. (5.3.4 (a) (i))
- Advice** Unable to open tail gate.
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear arm bush. (5.3.4 (a) (i))
- Advice** Offside Rear sill damaged.

MOT #11

2022-07-28 13:21

MOT test number

859499966513

Result**✓ Passed**

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii))
- Advice** Unable to open boot
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #10** 2022-07-28 10:47**MOT test number** 841921651739**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Unable to open boot**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #9** 2021-07-23 12:41**MOT test number** 497552438715**Result** ✓ Passed**MOT #8** 2020-07-30 15:22**MOT test number** 710390660855**Result** ✓ Passed**MOT #7** 2020-07-30 09:34**MOT test number** 175472020389**Result** ✗ Failed**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #6** 2019-07-30 10:50**MOT test number** 184917350448**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2018-07-16 14:05**MOT test number** 228035294975**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2018-07-16 09:16**MOT test number** 972946838635**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Fail** Offside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2017-07-17 09:52**MOT test number** 304257823576**Result** ✓ Passed**MOT #2** 2016-07-30 09:31**MOT test number** 385264920041**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)



MOT #1	2015-07-27 10:11
MOT test number	359598005204
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
3 August 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	3 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-07-31
Last registration	2023-08-04
Complete history	See info



Registration #1	2012-07-31	26 mi
Registration #2	2015-07-27	41.763 mi
Registration #3	2016-07-30	59.533 mi
Registration #4	2017-07-17	73.926 mi
Registration #5	2018-07-16	84.833 mi
Registration #6	2018-07-16	84.837 mi
Registration #7	2019-07-30	96.975 mi
Registration #8	2020-07-30	106.393 mi
Registration #9	2020-07-30	106.393 mi
Registration #10	2020-07-30	106.393 mi
Registration #11	2020-07-30	106.393 mi
Registration #12	2020-07-30	106.393 mi
Registration #13	2020-07-30	106.393 mi
Registration #14	2020-07-30	106.393 mi
Registration #15	2020-07-30	106.393 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	90%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1780 mm
Height	1470 mm
Length	4300 mm
Wheel base	2650 mm
Kerb weight	1306 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4FACZ456456