



report date: 2024-03-28

General information

Make	CITROEN
Model	BERLINGO HDI VTR
Colour	Blue
Year of manufacture	2012
Top speed	102 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	91 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	60.1 mpg
Consumption combined	54.3 mpg
CO2 emission	135 g/km
CO2 label	E





MOT history

MOT expiry date	2021-12-04
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	23
Total items failed	11

MOT #10	2020-12-03 12:58
MOT test number	446172481964
Result	✓ Passed
Next expiry date	2021-12-04

MOT #9	2020-12-03 11:42
MOT test number	725169615176
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm 205 65 15 (5.2.3 (e))
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #8	2019-12-05 10:29
MOT test number	830705791165
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7** 2018-11-22 11:56**MOT test number** 696500723497**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 205/65/15 (5.2.3 (e))
- Advice** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 205/65/15 (5.2.3 (e))
- Advice** Undertrays fitted
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 205/65/15 (5.2.3 (e))

MOT #6 2018-11-21 17:01**MOT test number** 511937408118**Result** ✗ Failed

- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 205/65/15 (5.2.3 (e))
- Fail** Nearside Front Macpherson strut pin or bush excessively worn top mount (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 205/65/15 (5.2.3 (e))
- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 205/65/15 (5.2.3 (e))
- Advice** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
- Advice** Undertrays fitted

MOT #5 2017-11-29 15:50**MOT test number** 630098735485**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit 205/65r15 (4.1.E.1)

**MOT #4** 2017-11-29 11:28**MOT test number** 487932439883**Result** ✗ Failed

- Fail** Offside Headlamp not working on dipped beam (1.7.5a)
- Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Slight bind to both rear brakes
- Fail** Offside Stop lamp not working (1.2.1b)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Wiper have not been tested
- Fail** Nearside Stop lamp not working (1.2.1b)
- Advice** Offside Rear Tyre worn close to the legal limit 205/65r15 (4.1.E.1)

MOT #3 2016-11-28 14:27**MOT test number** 577203285146**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2016-11-28 14:27**MOT test number** 626583105662**Result** ✗ Failed

- Pass with rectification** Registration plate lamp not working (1.1.C.1d)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2015-12-02 07:25
MOT test number	973591947938
Result	✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	HN62CUJ
Plate since	2019-03-28
Current registration	HN62CUJ
Plate since	2019-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2012-11-30
Last registration	2020-12-03
Complete history	See info



Registration #1	2012-11-30	23 mi
Registration #2	2015-12-02	43.920 mi
Registration #3	2016-11-28	55.313 mi
Registration #4	2016-11-28	55.313 mi
Registration #5	2017-11-29	64.058 mi
Registration #6	2017-11-29	64.058 mi
Registration #7	2018-11-29	72.777 mi
Registration #8	2018-11-29	72.777 mi
Registration #9	2019-11-29	72.777 mi
Registration #10	2019-11-29	72.777 mi
Registration #11	2020-12-03	72.777 mi

More info >



Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)

Dimensions & weight

Width	1810 mm
Height	1852 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1360 kg
Max. allowed weight	2040 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBEM0093050