



report date: 2024-03-29

General information

Make	FORD
Model	FUSION ZETEC TDCI
Colour	Black
Year of manufacture	-
Top speed	98 mph
0 - 60 mph	16.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	160 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-19
Pictures	10
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #15	2022-02-25 12:54
MOT test number	240513659515
Result	✓ Passed
Next expiry date	2023-03-15
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #14	2022-02-25 12:54
MOT test number	791765819030
Result	✗ Failed
Pass with rectification	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Pass with rectification	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #13	2021-03-16 15:52
MOT test number	507152948113
Result	✓ Passed
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Oil leak

**MOT #12** 2020-04-17 12:42**MOT test number** 606203069983**Result** ✓ Passed**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Parking brake efficiency only just met**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #11** 2019-04-13 11:18**MOT test number** 148483412290**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #10** 2018-04-10 16:06**MOT test number** 323976984089**Result** ✓ Passed**MOT #9** 2018-04-10 08:59**MOT test number** 262298198407**Result** ✗ Failed**Fail** Stop lamp not working both (1.2.1b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2017-04-14 14:09**MOT test number** 312530535922**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases centre section (7.1.2)**Advice** Oil leak

**MOT #7** 2017-04-14 09:55**MOT test number** 455240283944**Result** ✗ Failed**Advice** Oil leak**Fail** Nearside Rear Rear wheel bearing rough when rotated (2.6.1)**Advice** Exhaust has a minor leak of exhaust gases centre section (7.1.2)**MOT #6** 2016-04-14 13:04**MOT test number** 444466116051**Result** ✓ Passed**Advice** Centre Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #5** 2016-04-14 10:44**MOT test number** 596419397832**Result** ✗ Failed**Fail** Nearside Rear Rear wheel bearing has excessive play (2.6.2)**Advice** Centre Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #4** 2015-03-31 10:06**MOT test number** 917650495097**Result** ✓ Passed**MOT #3** 2014-03-18 15:52**MOT test number** 248177174056**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Direction indicator slightly discoloured (1.4.A.2f)



MOT #2	2013-04-03 14:32
MOT test number	418433993057
Result	✓ Passed
MOT #1	2012-09-10 14:11
MOT test number	565444852225
Result	✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	LD59WLL
Plate since	2019-03-29
Current registration	LD59WLL
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-09-30
Last registration	2022-02-25
Complete history	See info



Registration #1	2009-09-30	12 mi
Registration #2	2012-09-10	36.971 mi
Registration #3	2013-04-03	41.512 mi
Registration #4	2014-03-18	52.794 mi
Registration #5	2015-03-31	64.707 mi
Registration #6	2016-04-14	76.533 mi
Registration #7	2016-04-14	76.533 mi
Registration #8	2017-04-14	85.742 mi
Registration #9	2017-04-14	85.742 mi
Registration #10	2018-04-14	94.951 mi
Registration #11	2019-04-14	104.160 mi
Registration #12	2020-04-14	113.369 mi
Registration #13	2021-04-14	122.578 mi
Registration #14	2022-02-25	131.787 mi
Registration #15	2022-02-25	131.787 mi
Registration #16	2022-02-25	131.787 mi
Registration #17	2022-02-25	131.787 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1162 kg
Max. allowed weight	1640 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	9R24266
---------------	---------