



CITROËN




report date: 2024-03-28

General information

Make	CITROEN
Model	DISPATCH 1000 L1H1 ENTERPRISE P/V HDI
Colour	White
Year of manufacture	2013
Top speed	90 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	180 Nm at 1.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	45.6 mpg
Consumption combined	42.2 mpg
CO2 emission	177 g/km
CO2 label	I





MOT history

MOT expiry date	2021-03-30
MOT pass rate	56 %
MOT passed	5
Failed MOT tests	4
Total advice items	13
Total items failed	6

MOT #9	2020-03-31 07:40
MOT test number	317475778502
Result	✓ Passed
Next expiry date	2021-03-30

MOT #8	2020-03-30 09:17
MOT test number	817431110574
Result	✗ Failed
Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))	
MAJOR Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))	
Pass with rectification Stop lamp(s) not working eye level (4.3.1 (a) (ii))	
MAJOR Rear Exhaust system insecure (6.1.2 (a))	

MOT #7	2019-03-04 09:15
MOT test number	196313372131
Result	✓ Passed
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Engine cover fitted	

**MOT #6** 2019-03-02 11:30**MOT test number** 835093138095**Result** ✗ Failed**MAJOR** Central Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Front wiper blade securing clip broken**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MAJOR** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Engine cover fitted**MAJOR** Offside Front Position lamp not working (4.2.1 (a))**MOT #5** 2018-02-26 10:04**MOT test number** 503616555082**Result** ✓ Passed**MOT #4** 2018-02-26 10:04**MOT test number** 404069919817**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #3** 2017-03-16 12:45**MOT test number** 692713471440**Result** ✓ Passed



MOT #2	2017-03-16 12:45
MOT test number	375827124531
Result	✗ Failed
Pass with rectification	Stop lamp not working eye level (1.2.1b)
Pass with rectification	Offside Front position lamp(s) not working (1.1.A.3b)

MOT #1	2016-03-16 15:40
MOT test number	500876556875
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:
3 February 2021

X

MOT

Expired:
30 March 2021

Tax status	Expired at 3 February 2021
Days left	1181 days too late
MOT expiry date	30 March 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2013-03-21
Last registration	2020-03-31
Complete history	See info



Registration #1	2013-03-21	18 mi
Registration #2	2016-03-16	49.386 mi
Registration #3	2017-03-16	67.952 mi
Registration #4	2017-03-16	67.952 mi
Registration #5	2018-02-26	83.012 mi
Registration #6	2019-03-31	95.377 mi
Registration #7	2019-03-31	95.377 mi
Registration #8	2019-03-31	95.377 mi
Registration #9	2019-03-31	95.377 mi
Registration #10	2020-03-31	95.377 mi

More info >



Dimensions & weight

Width	1895 mm
Height	1942 mm
Length	4805 mm
Kerb weight	1673 kg
Max. allowed weight	2661 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Number of axles	2
Engine number	JBDF0029476