



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE LUNA 8V
Colour	Grey
Year of manufacture	2010
Top speed	111 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	147 Nm at 3.800 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	180 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-08-13
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-08-23
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	8
Total items failed	11

MOT #17	2023-08-16 15:52
MOT test number	453002015408
Result	✓ Passed
Next expiry date	2024-08-23

MOT #16	2023-08-16 14:20
MOT test number	925149678544
Result	✗ Failed
Fail	Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Offside Headlamp not working on main beam (4.1.1 (a) (ii))

MOT #15	2022-08-23 12:36
MOT test number	566318593123
Result	✓ Passed

MOT #14	2021-08-24 11:13
MOT test number	253710730844
Result	✓ Passed

**MOT #13**

2021-08-23 14:48

MOT test number

484881239171

Result**✗ Failed****Fail** Offside Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))**Fail** Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Fail** Offside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**MOT #12**

2021-01-14 09:41

MOT test number

854004487536

Result**✓ Passed****MOT #11**

2021-01-12 08:40

MOT test number

217617600934

Result**✗ Failed****Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Offside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Sill (5.3.6 (a) (i))**Fail** Nearside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Sill (5.3.6 (a) (i))**MOT #10**

2020-01-07 15:11

MOT test number

429433216369

Result**✓ Passed****Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #9** 2018-07-24 12:47**MOT test number** 362815554773**Result** ✓ Passed**MOT #8** 2017-07-18 11:16**MOT test number** 725699720515**Result** ✓ Passed**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**MOT #7** 2016-08-09 08:58**MOT test number** 185579281428**Result** ✓ Passed**MOT #6** 2015-08-10 11:00**MOT test number** 234308130572**Result** ✓ Passed**MOT #5** 2015-08-10 11:00**MOT test number** 473854169869**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2015-02-20 10:07**MOT test number** 908021055011**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Both rear and front left tyres cracking slightly



MOT #3	2014-02-19 11:15
MOT test number	488670654075
Result	✓ Passed
MOT #2	2013-02-08 11:08
MOT test number	945689733006
Result	✓ Passed
MOT #1	2013-02-08 11:08
MOT test number	357939333049
Result	✗ Failed
Pass with rectification	Offside Registration plate lamp not working (1.1.C.1d)
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
23 August 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	23 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 YD10XWW
Plate since	2019-06-29
Current registration	 YD10XWW
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-03-01
Last registration	2023-08-16
Complete history	See info



Registration #1	2010-03-01	21 mi
Registration #2	2013-02-08	27.317 mi
Registration #3	2014-02-19	37.146 mi
Registration #4	2015-02-20	47.996 mi
Registration #5	2015-08-10	52.696 mi
Registration #6	2015-08-10	52.696 mi
Registration #7	2016-08-09	55.478 mi
Registration #8	2017-07-18	58.444 mi
Registration #9	2018-07-24	60.909 mi
Registration #10	2019-08-20	63.377 mi
Registration #11	2019-08-20	63.377 mi
Registration #12	2019-08-20	63.377 mi
Registration #13	2019-08-20	63.377 mi
Registration #14	2019-08-20	63.377 mi
Registration #15	2019-08-20	63.377 mi
Registration #16	2019-08-20	63.377 mi
Registration #17	2019-08-20	63.377 mi
Registration #18	2019-08-20	63.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2515 mm
Kerb weight	1314 kg
Max. allowed weight	1680 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BFS 078357