





## General information

| Make                | MINI                      |  |
|---------------------|---------------------------|--|
| Model               | JOHN COOPER WORKS GP AUTO |  |
| Colour              | Grey                      |  |
| Year of manufacture | 2020                      |  |
| Top speed           | 165 mph                   |  |
| Gearbox             | 8 speed automatic         |  |

## Engine & fuel consumption

| Power                | 302 BHP             |
|----------------------|---------------------|
| Max. torque          | 450 Nm at 4.500 rpm |
| Engine capacity      | 1.998 cc            |
| Cylinders            | 4                   |
| Fuel type            | Petrol              |
| Consumption combined | 34.0 mpg            |
| CO2 emission         | 189 g/km            |
| CO2 label            | J                   |





## Internet history

Entry 1

Date Pictures 2021-08-05

12

19

Listing price

View report



source: cargurus.co.uk



## MOT history

| MOT expiry date    | 2024-08-31 |
|--------------------|------------|
| MOT pass rate      | 50 %       |
| MOT passed         | 1          |
| Failed MOT tests   | 1          |
| Total advice items | 8          |
| Total items failed | 1          |

| MOT #2    |   | 2023-09-01 10:47 |
|-----------|---|------------------|
| MOT test  | number  | 863506255378     |
| Result    |   | 🗸 Passed         |
| Next expi | ry date   | 2024-08-31       |
| Advice    | Offside Rear Tyre has a cut but not deep enough to reach the ply or cords | (5.2.3 (d) (i))  |
| Advice    | Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))              |                  |
| Advice    | Offside Rear Nail in tyre   |                  |

#### MOT #1 2023-08-31 11:42 944684738902 **MOT test number** Result **X** Failed Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i)) Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) **Advice** Offside Rear Nail in tyre Fail Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii)) Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) Advice Nearside Rear Nail in tyre



Tax & MOT check

| ✓<br>Taxed<br>Tax due:<br>1 August 2024 | ✓<br>MOT<br>Expires:<br>31 August 2024 |
|---|--|
| Tax status                              | Valid until 1 August                   |
| Days left                               | 93                                     |
| MOT expiry date                         | 31 August 2024                         |
| Full MOT history                        | See MOT history                        |

## Tax calculation

| Vehicle class                 | 48           |
|-------------------------------|--------------|
| Band                          | J            |
| First licence fee (12 months) | £ 1.040,00,- |
| Standard rate (12 months)     | £ 180,00,-   |
| Standard rate (6 months)      | £ 99,00,-    |
| Premium rate (12 months)      | £ 570,00,-   |
| Premium rate (6 months)       | £ 313,50,-   |





#### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |      |
|----------|------|
| Date     |      |
| Category | Lamp |
| Туре     |      |
| Damage 2 | AMPL |
| Date     |      |
| Date     | OLE  |
| Category | E.S. |
| Туре     |      |

#### Extra MINI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4 10.000 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4        |

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| xxxxxxxx  |             |
|---|-------------|
| ************  |             |
| ********  |             |
| *******   |             |
| ***********   |             |
| ********  |             |
|   | More info > |
| Plate changes   |             |
| See in this check if this MINI had different number plates. |             |
| Number of plates  | ,           |
| Current registration  |             |
| Plate since   |             |
| Carrent registration  |             |
| Plate since   |             |
|   |             |





#### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |


More info  $\rightarrow$ 





## Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 4          |
| First mileage registration | 2020-09-01 |
| Last registration          | 2023-09-01 |
| Complete history           | See info   |



| Registration #1 | 2020-09-01 | 11 mi      |
|-----------------|------------|------------|
| Registration #2 |            | 11.777 est |
| Registration #3 |            | 11.777 esi |
| Registration #4 |            | 11.319 est |

More info >




# RX70VDG report date: 2024-03-29

## Car features

| S0225  | Air conditioning |
|--------|------------------|
| S0295  |                  |
| S0482  |                  |
| \$0501 |                  |
| \$0566 |                  |
| \$0567 |                  |
| S0569  |                  |

## Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 79%             |
| Children       | 73%             |
| Pedestrian     | 66%             |
| Safety systems | 56%             |
| Overall rating | 71%             |
| Video          | see crash video |



| Dimensions & weight               |              |
|-----------------------------------|--------------|
| Width                             | 1762 mm      |
| Height                            | 1420 mm      |
| Length                            | 3879 mm      |
| Wheel base                        | 2495 mm      |
| Kerb weight                       | 1255 kg      |
| Max. allowed weight               | 1505 kg      |
| Additional information            |              |
| Fuel tank capacity                | 40           |
| Number of doors                   | 3            |
| Number of seats                   | 2            |
| Number of axles<br>CarCheck.co.uk | 2 page 10/10 |