





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT SE BUSINESS TDI BLUEMOTION TECHNOLOGY
Colour	White
Year of manufacture	2017
Top speed	135 mph
0 - 100 km/h	8.9 seconds
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 kW / 150 HP / 148 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	67.3 mpg
CO2 emission	110 g/km
CO2 label	В



CarCheck.co.uk page 1/12



Internet history

Entry 2

Date 2022-04-05

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 1

Date 2022-03-31

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-03-07
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	16
Total items failed	3

MOT #7		2024-03-08 11:18
MOT test	number	222508500185
Result		✓ Passed
Next expi	ry date	2025-03-07
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #6	2024-03-08 11:18
MOT test number	108144055248
Result	★ Failed
Pass with rectification (ii))	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b)
Advice Offside Rear Inn	er Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice Nearside Front I	nner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5	2023-03-03 14:52
MOT test number	606448151870
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT #4 2022-04-07 14:44

MOT test number 775561131217

Result \(\sqrt{Passed} \)

MOT #3 2021-09-21 15:05

MOT test number 480475667900

Result

Passed

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a)

(ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a)

(ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a)

(ii))

MOT #2 2021-09-21 10:09

MOT test number 107364307041

Result X Failed

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a)

(ii))

Advice Nearside Rear Nail in tyre

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a)

(ii))

CarCheck.co.uk page 4/12



GK67YND

report date: 2024-03-29

MOT #1 2020-09-22 11:16

MOT test number 866258652000

Result ✓ Passed

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Items removed from driver's view prior to test

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	7 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

GK67YND

report date: 2024-03-29

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report here.

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

EXECUTE OF THE PROPERTY OF THE

UK NE

More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-09-27
Last registration	2024-03-08
Complete history	See info



Registration #1	2017-09-27	8 mi
Registration #2	2020-09-22	37.708 mi
Registration #3	2021-09-21	43.845 mi
Registration #4	2021-09-21	43.845 mi
Registration #5		91.777 es
Registration #6		11.777 es
Registration #7		91.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		71.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	85%
Children	87%
Pedestrian	66%
Safety systems	76%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1832 mm
Height	1477 mm
Length	4767 mm
Wheel base	2791 mm
Kerb weight	1505 kg
Max. allowed weight	2100 kg

Additional information

Fuel tank capacity	66 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack co.uk	nago 12/13

CarCheck.co.uk page 12/12

Number of seats	5
Number of axles	2
Engine number	CRLB730395