



Mercedes-Benz

**BUI3XWG**


report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	B-CLASS B180 CDI BLUEEFFICIENCY SE
Colour	Blue
Year of manufacture	2013
Top speed	118 mph
0 - 100 km/h	10.7 seconds
0 - 60 mph	10.7 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	80 kW / 109 HP / 109 BHP
Max. torque	250 Nm at 1.400 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	72.4 mpg
Consumption combined	64.2 mpg
CO2 emission	112 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-10-27
Pictures	22
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://cargurus.co.uk)



## MOT history

MOT expiry date	2024-12-17
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	16
Total items failed	4

## MOT #12 2023-12-18 15:00

MOT test number 564075458707

Result ✓ Passed

Next expiry date 2024-12-17

**Advice** Rear Tyre slightly damaged/cracking or perishing Both nearside/offside dated 2017 (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Low outer edge plus cut in tread (5.2.3 (e))

## MOT #11 2022-11-07 12:35

MOT test number 572140953316

Result ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

## MOT #10 2021-10-29 12:49

MOT test number 807478695817

Result ✓ Passed

**MOT #9** 2020-11-06 14:48**MOT test number** 731729317477**Result** ✓ Passed**Advice** Nearside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Brake pedal wearing smooth Worn on corner . (1.1.2 (c))**Advice** Offside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #8** 2020-10-22 09:19**MOT test number** 858211858673**Result** ✗ Failed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Brake pedal wearing smooth (1.1.2 (c))**MOT #7** 2019-05-15 15:00**MOT test number** 642559134708**Result** ✓ Passed**Advice** Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Front wiper blades slightly smearing screen .**MOT #6** 2019-05-15 14:23**MOT test number** 355066769704**Result** ✗ Failed**Advice** Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Front wiper blades slightly smearing screen .**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

**MOT #5** 2018-05-16 16:04**MOT test number** 369190580872**Result** ✓ Passed**Advice** Front wiper blades slightly smeary**MOT #4** 2018-05-16 12:34**MOT test number** 599343938425**Result** ✗ Failed**Advice** Front wiper blades slightly smeary**Fail** Offside Side repeater not working (1.4.A.2c)**MOT #3** 2017-05-31 08:35**MOT test number** 440431952073**Result** ✓ Passed**MOT #2** 2017-05-30 08:18**MOT test number** 903808453505**Result** ✗ Failed**Fail** Central Stop lamp not working (1.2.1b)**MOT #1** 2016-06-13 06:02**MOT test number** 135678926234**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
17 December 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	17 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history


Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 <b>BU13XWG</b>
Plate since	2019-03-28
Current registration	 <b>BU13XWG</b>
Plate since	2019-03-28

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-05-24
Last registration	2023-12-18
Complete history	<a href="#">See info</a>



Registration #1	2013-05-24	10 mi
Registration #2	2016-06-13	42.531 mi
Registration #3	2017-05-30	50.625 mi
Registration #4	2017-05-31	50.625 mi
Registration #5	2018-05-16	62.125 mi
Registration #6	2018-05-16	62.126 mi
Registration #7	2019-05-15	73.724 mi
Registration #8	2019-05-20	95,377 mi
Registration #9	2019-05-20	95,377 mi
Registration #10	2019-05-20	95,377 mi
Registration #11	2019-05-20	95,377 mi
Registration #12	2019-05-20	95,377 mi
Registration #13	2019-05-20	95,377 mi
Registration #14	2019-05-20	95,377 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	81%
Pedestrian	56%
Safety systems	86%
Overall rating	85%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2010 mm
Height	1557 mm
Length	4359 mm
Wheel base	2699 mm
Kerb weight	1505 kg
Max. allowed weight	2025 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	65190131698133